

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTCarlsbad Field Office  
NMOC ArtesiaFORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.  
NMLC028784C

6. If Indian, Allottee or Tribe Name

**SUBMIT IN TRIPLICATE - Other instructions on page 2**7. If Unit or CA/Agreement, Name and/or No.  
NMNM88525X8. Well Name and No.  
BURCH KEELY UNIT 940H9. API Well No.  
30-015-44080-00-S110. Field and Pool or Exploratory Area  
BURCH KEELY-GLORIETA-UPR YESC11. County or Parish, State  
EDDY COUNTY, NM

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator  
COG OPERATING LLCContact: SANDY BALLARD  
E-Mail: sballard@concho.com3a. Address  
600 W ILLINOIS AVENUE  
MIDLAND, TX 797013b. Phone (Include area code)  
Ph: 432-686-4373

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 13 T17S R29E SENE 1650FNL 195FEL  
32.837135 N Lat, 104.019783 W Lon

MAR 11 2019

RECEIVED

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Venting and/or Flaring
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Burch Keely Unit 940H  
Burch Keely Unit 13A  
(Permit approval: Electronic Submission #431877)

Actual gas flared for this battery for 8/30/2018 TO 11/28/2018 is as follows:

Aug  
Total for Battery = 0 MCF  
Sept  
Total for Battery = 4887 MCF  
Oct  
Total for Battery = 3674 mcf

Accepted for record  
NMOC 3/12/19  
AB

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #455318 verified by the BLM Well Information System

For COG OPERATING LLC, sent to the Carlsbad

Committed to AFMSS for processing by PRISCILLA PEREZ on 02/22/2019 (19PP1092SE)

Name (Printed/Typed) SANDY BALLARD

Title SENIOR ADMINISTRATIVE ASSISTANT

Signature (Electronic Submission)

Date 02/20/2019

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

ACCEPTED FOR RECORD

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FEB 22 2019

/s/ Jonathon Shepard

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

**Additional data for EC transaction #455318 that would not fit on the form**

**32. Additional remarks, continued**

Nov

Total for Battery = 0 MCF

NUMBER OF WELLS TO FLARE: (22)

BURCH-KEELY UNIT 385 30-015-33795

BURCH-KEELY UNIT 420 30-015-36180

BURCH-KEELY UNIT 505 30-015-39438

BURCH-KEELY UNIT 508 30-015-39313

BURCH-KEELY UNIT 509 30-015-39439

BURCH-KEELY UNIT 512 30-015-39314

BURCH-KEELY UNIT 513 30-015-39440

BURCH-KEELY UNIT 517 30-015-39441

BURCH-KEELY UNIT 519 30-015-40690

BURCH-KEELY UNIT 520 30-015-39315

BURCH-KEELY UNIT 524 30-015-39518

BURCH-KEELY UNIT 525 30-015-39754

BURCH-KEELY UNIT 527 30-015-40315

BURCH-KEELY UNIT 530 30-015-39519

BURCH-KEELY UNIT 531 30-015-40316

BURCH-KEELY UNIT 532 30-015-40317

BURCH-KEELY UNIT 533 30-015-40318

BURCH-KEELY UNIT 536 30-015-39520

BURCH-KEELY UNIT 930H 30-015-40969

BURCH-KEELY UNIT 931H 30-015-42761

BURCH-KEELY UNIT 933H 30-015-40970

BURCH-KEELY UNIT 940H 30-015-44080

Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT PLANT SHUT DOWN DUE TO HLP OR PLANT MAINTENANCE