Submit One Copy To Appropriate District	State of New Mexico	Form C-103
District I RECEIVED Energy, Minerals and Natural Resources		Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-015-03569
District II 811 S. First St., Artesia, NM 88210 MAR 2 2 2091 CONSERVATION DIVISION District III		5. Indicate Type of Lease
		STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa F., NM II-ARTESIA C 87505	.C.D . Santa PC, 10101 87505	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		CONTINENTAL STATE
1. Type of Well: X Oil Well Gas Well Other		8. Well Number #9
2. Name of Operator EOG RESOURCES, INC		9. OGRID Number 7377
3. Address of Operator		10. Pool name or Wildcat
PO BOX 2267 MIDLAND, TEXAS 79702		
4. Well Location	he SOUTH line and 220 fast from the EA	ST line
Unit Letter <u>P</u> : <u>330</u> feet from the SOU <u>TH</u> line and <u>330</u> feet from the <u>EAST</u> line Section 9 Township <u>19S</u> Range <u>29E</u> NMPM County <u>EDDY</u>		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
NOT REPORTED 'GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTIO		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
		_
OTHER: Image: Construction of the constr		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u>		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment. Burned Cable Not Romanus		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. 32, L192/396 104.07202/65 All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
		oved. (Poured onsite concrete bases do not have
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrast	ructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE King Mudder	TITLE: REGULATORY SP	ECIALIST DATE 3/20/2019
TYPE OR PRINT NAME: KAY MADDOX	E-MAIL: kay_maddox@eogresources	.com PHONE: _432-686-3658
For State Use Only DENIED	DEMIE	GC
APPROVED BY:	TITLE	DATE 3/28/19

APPROVED BY: Conditions of Approval (if any):