State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen **Cabinet Secretary**

District II - Artesia, NM

Heather Riley, Division Director Oil Conservation Division



Matthias Sayer Deputy Cabinet Secretary	CONSERVATION OFFICE
	Date: 12/10/18
	API# 30-015-44851
A Mechanical Integrity Test (M.I.T.) was performed	on, Well Hood SWD OOI
M.I.T. is successful, the original chart has been rescan of the chart with an attached Original C-103 Fo District NMOCD field office. A scanned image will approximate www.emnrd.state.nm.us/ocd/OCDOnllne.htm 7 to 10	etained by the Operator on site. Send a legible rm indicating reason for the test, via post mail to bear online via NMOCD website,
M.I.T. is unsuccessful, the original chart is returned operator is to schedule for a re-test within a 90-day in non-compliance, all dates and requirements of the No expectation of extension should be construed	period. If this is a test of a repaired well currently e original are still in effect.
M.I.T. for Temporary Abandonment, shall incl the location of the CIBP and any other tubular goods status timeline.	ude a detailed description on Form C-103 , including in the well including the Operator's request for TA
M.I.T. is successful, after the secondary reque Operator has within a 30-day period from the M.I.T. to the Chart, including a detailed description of the repair compliance be closed.	o submit a current C-103 along with a legible scan of
M.I.T. is successful , Initial of an injection well, y 30 days. A C-103 form must include a detailed descrithe position of the packer, tubing Information, the d Injection volume.	iption of the work performed on this well Including
Please contact Rusty Klein at 575-748-1283 x109 for requirements are in place prior to injection process.	verification to ensure documentation
If I can be of additional assistance, please feel fre	e to contact me at (575) 748-1283 ext. 114.
Thank You,	
Gilbert Cordero, Staff Manager EMNRD-O.C.D.	