

State of New Mexico  
Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham  
Governor

Sarah Cottrell Propst  
Cabinet Secretary Designate

Todd E. Leahy, JD, PhD  
Deputy Secretary

Gabriel Wade, Acting Director  
Oil Conservation Division



Date: 3-19-19

API# 30-015-26190

A **Mechanical Integrity Test (M.I.T.)** was performed on, Well East land Queen #15

**M.I.T. is successful**, the original chart has been retained by the Operator on site. Send a **legible** scan of the chart with an attached **Original C-103 Form** indicating reason for the test, via post mail to District NMOCD field office. A scanned image will appear online via NMOCD website, [www.emnrd.state.nm.us/ocd/OCDOnline.htm](http://www.emnrd.state.nm.us/ocd/OCDOnline.htm) 7 to 10 days after postdating.

**M.I.T. is unsuccessful**, the original chart is returned to the Operator. Repairs will be made, Operator is to schedule for a re-test within a 90-day period. If this is a test of a repaired well currently in non-compliance, all dates and requirements of the original are still in effect.  
**No expectation of extension should be construed because of this test.**


**M.I.T. for Temporary Abandonment**, shall include a detailed description on **Form C-103**, including the location of the CIBP and any other tubular goods in the well including the Operator's request for TA status timeline.

**M.I.T. is successful**, after the secondary request of a scheduled M.I.T. is performed. Therefore, Operator has within a 30-day period from the M.I.T. to submit a current C-103 along with a legible scan of the Chart, including a detailed description of the repair(s). **Only after receipt of the C-103 will the non-compliance be closed.**

**M.I.T. is successful**, Initial of an injection well, you must submit a **form C-103** to NMOCD within 30 days. A **C-103 form** must include a detailed description of the work performed on this well including the position of the packer, tubing Information, the date of first Injection, the tubing pressure and Injection volume.

Please contact **Rusty Klein** at **575-748-1283 x109** for verification to ensure documentation requirements are in place prior to injection process.

**If I can be of additional assistance, please feel free to contact me at (575) 748-1283 ext.**

Thank You,  
  
Dan Smolik, Compliance Officer  
EMNRD-O.C.D.  
District II – Artesia, NM