RECEIVED

MAY	1	7	201	19
-----	---	---	-----	----

		WI/11 4	2010			
Submit One Copy To Appropriate District Office District I	State of New M Energy, Minerals and Nat	exico DISTRICT II-ART	ESIAO.C.D.	Form C-103 Revised November 3, 2011		
1625 N. French Dr., Hobbs, NM 88240 District II	NM 88240			30-015-36685		
811 S. First St., Artesia, NM 88210 District III	88210 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8		6. State Oil & Gas Lease No.			
1220 S. St. Françis Dr., Santa Fe, NM 87505			36900			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name of Unit Agreement Name RDX 16			
PROPOSALS.) 1. Type of Well: I Oil Well Gas Well Other			8. Well Number	005		
2. Name of Operator RKI EXPL	ORATION & PRODL	JCTION, LLC	9. OGRID Numbe	^r 246289		
3. Address of Operator 3500 ONE WILLIAMS CENTER MD 35 TULSA, OK 74172			10. Pool name or Wildcat BRUSHY DRAW; DELAWARE, EAST			
4. Well Location Unit LetterJ2310 feet from theS line and 2310 feet from theE line						
Section 16 Township 26S Range 30E NMPM County EDDY						
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,076' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
	-		, 			
NOTICE OF INTENTION TO: SUBS PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRII PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT			LING OPNS 🔲 🛛 F	ORT OF:		
OTHER:		Location is rea	ady for OCD inspec	tion after P&A		
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 						
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.						
The location has been leveled as no other production equipment.	early as possible to original grou	nd contour and has b	een cleared of all ju	nk, trash, flow lines and		
 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed 						
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)						
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 						
retrieved flow lines and pipelines.						
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.						
When all work has been completed, return this form to the appropriate District office to schedule an inspection.						
SIGNATURE		ermit Technici	an IID	ATE 05/14/2019		
TYPE OR PRINT NAME Caitlin O' For State Use Only	Hair E-MAIL:	caitlin.ohair@wp	xenergy.com PH	IONE: 539-573-3527		
APPROVED BY:	TITLE_	Stat M	,I	DATE 5/20/19		

,