RECEIVED

	New Mexico	Form C-103
District I District II Strict II Strict II Strict II Strict II Strict III District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV District IV ATTESIA OF DEPTH		Revised November 3, 2011 WELL API NO.
		30-005-61986
		5. Indicate Type of Lease
		STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		o. State on the day Zease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Spool SU
PROPOSALS.)		8. Well Number
1. Type of Well: ☐Oil Well ☐ Gas Well ☒ Other P&A 2. Name of Operator		9. OGRID Number
EOG Resources, Inc.		7377
3. Address of Operator		10. Pool name or Wildcat
104 South Fourth Street, Artesia, NM 88210		Pecos Slope; Abo
4. Well Location		
Unit Letter D 660 feet from the Section 23 Township 7S	North line and Range 25E	660 feet from the West line NMPM Chaves County
Section 23 Township 7S Range 25E NMPM Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3,704' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
PULL OR ALTER CASING		
OTHER: Location is ready for OCD inspection after P&A		
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
5 7 m		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
other production equipment. Burned Plastic Liner Not Nemoved Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
All metal bolts and other materials have been removed. P	ortable bases have been remo	ved. (Poured onsite concrete bases do not have
to be removed.) Riser's Not Removed All other environmental concerns have been addressed as per OCD rules.		
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines. No, active pipeline(s) within YPC gas system.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
() a A (). 0		
SIGNATURE	TITLE: Environmental Super	visor DATE 6/14/2019
TYPE OR PRINT NAME: Robert Asher	E-MAIL: <u>robert_asher @eog</u>	resources.com PHONE: 575-748-1471
For State Use Only	DEN	GC ,
APPROVED BY:	TITLE	DATE 6/24/19
Conditions of Approval (if any):	*****	