District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Form C-144 March 12, 2004

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Pit or Below-Gra	de Tank Registration or Closu	<u>re</u>
Is pit or below-grade tan	k covered by a "general plan"? Yes No or below-grade tank Closure of a pit or below-gra	⊠ de tank ⊠
Type of action. Registration of a pirc	or below-grade tank [1] Closure of a pit of below-gra	RIE MIK 💆
	272_443_6489_e-mail address: zfarris@cimarex.com	An annual and the State of the
Address: P.O. Box 140907, Irving, Tx 75014-0907		
	34199 U/L or Qtr/Qtr_GSec_13T_2	
County: Eddy Latitude 320757.47 N Longitude 10414	131.17 W NAD: 1927 ▼ 1983 ☐ Surface Or	wner Federal X State 🗌 Private 🗍 Indian 🗍
Pit	Below-grade tank	
Type: Drilling ☑ Production ☐ Disposal ☐	Volume:bbl Type of fluid:	
Workover Emergency	Construction material:	_
Lined X Unlined	Double-walled, with leak detection? Yes If no	et, explain why not.
Liner type: Synthetic X Thickness 12 mil Clay Volume		
bbl		
Depth to ground water (vertical distance from bottom of pit to seasonal high	Less than 50 feet	(20 points)
water elevation of ground water.)	50 feet or more, but less than 100 feet	(10 points)
>70' See water well record	100 feet or more	(0 points)
Wellhead protection area: (Less than 200 feet from a private domestic	Yes	(20 points)
water source, or less than 1000 feet from all other water sources.)	No.	(0 points)
The second secon		
Distance to surface water: (horizontal distance to all wetlands, playas,	Less than 200 feet	(20 points)
irrigation canals, ditches, and perennial and ephemeral watercourses.)	200 feet or more, but less than 1000 feet	(10 points)
	1000 feet or more	(0 points)
	Ranking Score (Total Points)	-0-
If this is a pit closure: (1) attach a diagram of the facility showing the pit	s relationship to other equipment and tanks. (2) Indic	ate disposal location:
onsite 🛛 offsite 🗌 If offsite, name of facility	(3) Attach a general description of remedial act	tion taken including remediation start date and er
date. (4) Groundwater encountered: No 🔀 Yes 🗔 If yes, show depth bel	ow ground surfaceft. and attach samp	ele results. (5) Attach soil sample results and a
diagram of sample locations and excavations.		
I hereby certify that the information above is true and complete to the best of been will be constructed or closed according to NMOCD guidelines	a general permit 🔲, or an (attached) alternative C	CD-approved plan .
Printed Name/Title Zeno Farris Manager Operations Administration	_ Signature _ eno + am	, <u></u>
Your certification and NMOCD approval of this application/closure does no otherwise endanger public health or the environment. Nor does it relieve the regulations.	t relieve the operator of liability should the contents o	of the pit or tank contaminate ground water or
Approval: MAY 0 4 2006	100	
Printed Name/Title	Signature	

Surface Pit Closure Plan

Pit Parameters

Well site: Federal 13 Com #4

Legal Description: 1620 FNL, 1440 FWL

46 Section: 13 25S 26E

320757.47 N 1041431.17 W 30-015-34199 Eddy County, New Mexico

The reserve pit insitu on this leasehold is being permitted to close as per New Mexico OCD "Pit and Below Grade Tank Guidelines" dated November 1, 2004.

This pit was excavated and formed to the dimensions roughly 120 feet x 115 feet x 6 feet deep. A 12 mil membrane liner and pad was used to prevent leakage to the surface soils. A visual examination of the membrane liner indicates that the liner has maintained its integrity.

The well bore penetrated a salt/anhydrite section causing the drilling fluid to saturate to a concentration weight of > 9.5 ppg.

After the drilling and completion phase of this project, the water phase of the pit contents were pumped and hauled to an approved water injection facility. The remaining solids were mechanically pulled to the corners of the containment area to allow them to dry and leach out as much liquid phase as possible. Again these liquids we hauled to an approved water injection facility. It is estimated that the volume of solids remaining are to +/- 1900 yards. The burial cell is to

be excavated and lined with a minimum 12 mil membrane that complies with ASTM Standard(s): D 5747, D 5199, D-5994, and D-4833. The cuttings will be loaded as to allow for > 36" freeboard to ground level. After the cuttings are loaded, the 12 mil liner will be folded over the top. A 20 mil minimum thickness liner meeting the minimum requirements as outlined in ASTM Standard Methods: D-5747, D-5199, D-5994, D-4833; will be used to cap and cover to an extended area that exceeds three feet in all directions from the edge of the burial cell. This cap will be constructed as to slope and allow for water runoff from burial cell.

A minimum of 36" of top soil will be used to cover the burial cell. This soil must be capable of supporting native plant growth. A seed mixture will be used as to conform to local BLM as well as New Mexico OCD requirements. The seeding and propagation of required native plants will be monitored as to insure that growth is reestablished.

After the drilled solids are buried, the natural contour of the surrounding soils will be mechanically shaped as prevent erosion of the well site until vegetation is established.

The caliches and soils will be pulled from the well site pad to allow for a 200 X 300 pad dimension for production use. The remaining materials will be used to maintain lease roads and other drill sites

File	Number:	
		

NEW MEXICO OFFICE OF THE STATE ENGINEER WELL RECORD

1. OWNER OF WELL	
Name: Gruy Petroleum Management Co.	Work Phone: 972-443-6489
Contact: Zeno Farris Address: P.O. Box 140907	Home Phone:
Address: P.O. Box 140907	
City: Irving	State: TX Zip: 75014-0907
O TOGETON OF WITH A DOLLAR A LANGUAGE	L
2. LOCATION OF WELL(A,B,C,or D required,E or F if : A1/41/41/4 Section: 13	
in Eddy	
B. X =feet, Y =	
Zone in the	Grant.
U.S.G.S. Quad Map	
C. Latitude: 32 d 07 m 57.47 s Long	itude: 104 d 14 m 31.17 s
D. East(m), North(m),	UTM Zone 13, NAD(27 or 83)
E. Tract No, Map Noof the	Hydrographic Survey
F. Lot No, Block No of Unit/Trac	
Subdivision recorded i	in County.
G. Other:	
H. Give State Engineer File Number if existing world in the state of t	e11:
3. DRILLING CONTRACTOR	
License Number: WD-1456	
Name: White Drilling Company, Inc.	Work Phone: 325-893-2950
Agent: John W. White	Home Phone: 325-893-2950
Mailing Address: P.O. Box 906	
City: Clyde	State: TX Zip: 79510
4. DRILLING RECORD: FEDERAL 13 COM 4	
Drilling began: 3/21/06 ; Completed: 3/22/06	: Type tools: Air Rotary :
Size of hole: 6 1/8 in.; Total depth of well: 7	
Completed well is: shallow (shallow, a	
Depth to water upon completion of well: Dry	ft.
File Number: Form: wr-20 page 1 of 4	Trn Number:

(inches) per ft. per in. Top Bottom (feet) From 2.0 Sch. 40 4.0 0.0 60.0 60.0		(GPM)					ption of bearing f	water-	in feet		То	From
Depth in Feet Hole Sacks Cubic Feet Method of Placement From To Diameter of mud of Cement 70.0 10.0 61/8 19.0 Bentonite Pellets 10.0 0.0 61/8 6.0 1.997 Hand Mix - cement PLUGGING RECORD Plugging Contractor: Address: Plugging Method: Date Well Plugged: Plugging approved by: State Engineer Representative	70.0	60.0			eet}	60.0 10.0	Bottom 60.0	Top	per in. 4.0	Pounds per ft. Sch. 40	er	Diameto (inche: 2.0
PLUGGING RECORD Plugging Contractor: Address: Plugging Method: Date Well Plugged: Plugging approved by: State Engineer Representative			ets nent	onite Pelle Mix - cem	Bente	nt 	of Ceme	Sacks of mud 19.0 6.0	Hole ameter /8	Feet 0.0 6 6	in To	Depth From 70.0
									:	Address ng Method l Plugged	uggi Wel	Pl [.] Date
Top Bottom 1			.ive		nt	: Cemer	ic Feet of	om	Botte	Top 1 2 3 4		

File Number:

File	Number:	

NEW MEXICO OFFICE OF THE STATE ENGINEER WELL RECORD

9. LOG OF HOLE: FEDERAL 13 COM 4

Depth in	feet To	Thickness in feet	Color and Type of Material Encountered
From	2.0	2.0	Reddish brown sandy clay.
0.0 2.0	5.0	3.0	Caliche.
5.0	11.0	6.0	Limestone.
11.0	16.0	5.0	Caliche.
	20.0	4.0	Tannish brown silty shale gravel @ 18'.
16.0	26.0	6.0	Reddish brown silty shale.
20.0	28.0	2,0	Limestone.
26.0	42.0	14.0	Reddish brown silty shale.
28.0			Limestone.
42.0	44.0	2.0	Reddish brown silty shale.
44.0	46.0	2.0	Limestone.
46.0	50.0	4.0	Daddish brown allti abole
50.0	54.0	4.0	Reddish brown silty shale.
54.0	56.0	2.0	Limestone.
56.0	57.0	1.0	Reddish brown clay.
57.0	62.0	5.0	Reddish brown silty shale.
62.0	66.0	4.0	Limestone.
66.0	70.0	4.0	Reddish brown silty shale.
	-		
,	-		
	-		

File Number:		Trn Number:	
Form: wr-20	page 3 of 4		

File Number:	
OFFICE OF THE STATE ENGINEER WELL RECORD	
DR EXPLANATIONS: FEDERAL 13 COM 4	

	,		
	<u>.</u>		
The undersigned	hereby certifies the	at, to the best of his knowledge a	ınd
belief, the fore hole.	going is a true and	correct record of the above descr	ibec
note.	\sim		
		2/29/06	
D	riller	(mm/dd/year)	
	•		
			===:
	FOR STATE E	NGINEER USE ONLY	
Ouad : FWL	:FSL :Use	Location No.	
		· · · · · · · · · · · · · ·	

NEW MEXICO