

Submit One Copy To Appropriate District JN 2 1 2019 State of Office	New Mexico	Form C-103
District I Energy, Minerals and Natural Resources		Revised November 3, 2011
1625 N. French Dr., Hobbs, NM STAICT II ARTESIAO.C.D.		WELL API NO.
District II 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-015-10740
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE ☐ FEE ☒
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Yates AS Fee 8. Well Number
1. Type of Well: ☐ Oil Well ☐ Gas Well ☐ Other		1
2. Name of Operator		9. OGRID Number
EOG Resources, Inc.		7377
3. Address of Operator 104 South Fourth Street, Artesia, NM 88210		10. Pool name or Wildcat
		Penasco Draw; SA-Yeso
4. Well Location		
Unit Letter <u>K</u> : <u>2310</u> feet from the		feet from the <u>West</u> line
	18S Range 25E	NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3467' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
PULL OR ALTER CASING		
OTHER:	□ □ □ I continu in re	adv for OCD inappartian after DSA
OTHER: Description Descri		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production assument. Metal or location removed		
other production equipment. Metal on location removed. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. Battery still active, Yates AS Fee #4 producing into battery.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.) Buried wire by well marker removed. All other environmental concerns have been addressed as per OCD rules.		
An other cirvifolimental concerns have been addressed as per OCD fules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE CARONICO O	TITLE: Environmental Sup-	ervisor DATE 6/21/2019
	E-MAIL: Robert Asher@eo	gresources.com PHONE: 575-748-4217
For State Use Only	- 1 6	·藏化 , , , , ,
APPROVED BY:	TITLES TAT My	DATE 6/28/19
Conditions of Approval (if any):		