Do not use th	is form for proposals to	GENERATISDAD F RTS ON WELLS drill or to re-find and A			
abandoned we	II. Use form 3160-3 (AP	D) for such proposals.	TIESIA 6. If Indian, Allotte	ee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well Structions on page 2 Other			7. If Unit or CA/A	greement, Name and/or No.	
			8. Well Name and No. SUNRISE MDP1 8-5 FEDERAL COM 1731		
		SARAH E CHAPMAN HAPMAN@OXY.COM	9. API Well No. 30-015-4493	1-00-X1	
3a. Address 5 GREENWAY PLAZA SUITE 110 HOUSTON, TX 77046-0521		3b. Phone No. (include area code) Ph: 713-350-4997		or Exploratory Area GE-WOLFCAMP (GAS)	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description		)	11. County or Paris	11. County or Parish, State	
Sec 17 T24S R31E NENW 194FNL 1614FWL 32.224060 N Lat, 103.803169 W Lon			EDDY COUN	ITY, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent	□ Acidize	Deepen	Production (Start/Resume)	U Water Shut-Off	
	Alter Casing	Hydraulic Fracturing	Reclamation	Well Integrity	
🛛 Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Final Abandonment Notice	<ul> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	Plug and Abandon Plug Back	Temporarily Abandon Water Disposal	Workover Operatio	
Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for f RUPU 5/3/19, RIH & cleanout good test. RIH & perf from 215 20514-20326, 20299-20110, 2	oandonment Notices must be fil inal inspection. to PBTD @ 21664'. Pres 589-21400, 21374-21188 20084-19895, 19869-1968	ed only after all requirements, includ sure test 5-1/2" csg to 9800# , 21159-20970, 20944-20755, 30, 19656-19465, 19439-1925	ling reclamation, have been complete for 30 minutes, 20729-20540, 50, 19224-19035,	3160-4 must be filed once	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f RUPU 5/3/19, RIH & cleanout good test. RIH & perf from 215	andonment Notices must be fil inal inspection. to PBTD @ 21664'. Pres 589-21400, 21374-21188 20084-19895, 19869-1968 18579-18390, 18364-1817 17074-16885, 16859-1667 15569-15380, 15354-1516 14064-13875, 13846-1366 12559-12370, 12344-1216 0g slickwater and 1000g	ed only after all requirements, includ sure test 5-1/2" csg to 9800#, 21159-20970, 20944-20755, 30, 19656-19465, 19439-1925 75, 18149-17965, 17934-1774 70, 16642-16455, 16429-1624 35, 15139-14950, 14924-1473 50, 13636-13445, 13419-1323 55, 12129-11940, 11914-1172	ting reclamation, have been complete for 30 minutes, 20729-20540, 50, 19224-19035, 51, 17719-17530, 50, 16214-16025, 55, 14709-14520, 50, 13204-13015, 52, Total 1150 holes. sand. 5/30/19 RD	3160-4 must be filed once	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f RUPU 5/3/19, RIH & cleanout good test. RIH & perf from 21! 20514-20326, 20299-20110, 2 19009-18820, 18794-18605, 1 17504-17315, 17286-17100, 1 15999-15810, 15784-15597, 1 14494-14305, 14252-14090, 1 12989-12799, 12774-12585, 1 Frac in 46 stages w/ 1434951	bandonment Notices must be fil inal inspection. to PBTD @ 21664'. Pres 589-21400, 21374-21188 20084-19895, 19869-1966 18579-18390, 18364-1817 17074-16885, 16859-1667 15569-15380, 15354-1516 14064-13875, 13846-1366 12559-12370, 12344-1215 Og slickwater and 1000g t t for initial potential.	ed only after all requirements, includ sure test 5-1/2" csg to 9800# , 21159-20970, 20944-20755, 30, 19656-19465, 19439-1925 75, 18149-17965, 17934-1774 70, 16642-16455, 16429-1624 35, 15139-14950, 14924-1473 360, 13636-13445, 13419-132 55, 12129-11940, 11914-1172 7.5% HCl acid w/ 19294757# GCC $25$ Accepted for record - f	ling reclamation, have been complete for 30 minutes, 20729-20540, 50, 19224-19035, 15, 17719-17530, 10, 16214-16025, 55, 14709-14520, 55, 13204-13015, 55. Total 1150 holes. sand. 5/30/19 RD	B160-4 must be filed once and the operator has ECENED	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f RUPU 5/3/19, RIH & cleanout good test. RIH & perf from 219 20514-20326, 20299-20110, 2 19009-18820, 18794-18605, 1 17504-17315, 17286-17100, 1 15999-15810, 15784-15597, 1 14494-14305, 14252-14090, 1 12989-12799, 12774-12585, 1 Frac in 46 stages w/ 14349511 Schlumberger, RIH & cleanou	andonment Notices must be fil inal inspection. to PBTD @ 21664'. Pres 589-21400, 21374-21188, 20084-19895, 19869-1966 18579-18390, 18364-1817 17074-16885, 16859-1651 15569-15380, 15354-1516 12559-15380, 15354-1516 12559-12370, 12344-1216 0g slickwater and 1000g for initial potential.	ed only after all requirements, includ sure test 5-1/2" csg to 9800# , 21159-20970, 20944-20755, 30, 19656-19465, 19439-1925 75, 18149-17965, 17934-1774 70, 16642-16455, 16429-1624 35, 15139-14950, 14924-1473 30, 13636-13445, 13419-1323 35, 12129-11940, 11914-1172 7.5% HCI acid w/ 19294757# GCC C25 Accepted for record - f MCORPORATED, sent to the	ling reclamation, have been complete for 30 minutes, 20729-20540, 50, 19224-19035, 55, 17719-17530, 60, 13204-16025, 55, 14709-14520, 50, 13204-13015, 51. Total 1150 holes. sand. 5/30/19 RD DISTRICT	B160-4 must be filed once and the operator has ECENED	
following completion of the involved testing has been completed. Final At determined that the site is ready for f RUPU 5/3/19, RIH & cleanout good test. RIH & perf from 21% 20514-20326, 20299-20110, 2 19009-18820, 18794-18605, 1 17504-17315, 17286-17100, 1 15999-15810, 15784-15597, 1 14494-14305, 14252-14090, 1 12989-12799, 12774-12585, 1 Frac in 46 stages w/ 1434951 Schlumberger, RIH & cleanou	andonment Notices must be fil inal inspection. to PBTD @ 21664'. Pres 589-21400, 21374-21188, 20084-19895, 19869-1966 18579-18390, 18364-1817 17074-16885, 16859-1651 15569-15380, 15354-1516 12559-15380, 15354-1516 12559-12370, 12344-1216 0g slickwater and 1000g for initial potential.	ed only after all requirements, includ sure test 5-1/2" csg to 9800# , 21159-20970, 20944-20755, 30, 19656-19465, 19439-1925 75, 18149-17965, 17934-1774 70, 16642-16455, 16429-1624 35, 15139-14950, 14924-1473 360, 13636-13445, 13419-1323 355, 12129-11940, 11914-1172 7.5% HCl acid w/ 19294757# Gcccccccccccccccccccccccccccccccccccc	ling reclamation, have been complete for 30 minutes, 20729-20540, 50, 19224-19035, 55, 17719-17530, 60, 13204-16025, 55, 14709-14520, 50, 13204-13015, 51. Total 1150 holes. sand. 5/30/19 RD DISTRICT	B160-4 must be filed once and the operator has ECENED	
following completion of the involved testing has been completed. Final At determined that the site is ready for f RUPU 5/3/19, RIH & cleanout good test. RIH & perf from 21% 20514-20326, 20299-20110, 2 19009-18820, 18794-18605, 1 17504-17315, 17286-17100, 1 15999-15810, 15784-15597, 1 14494-14305, 14252-14090, 1 12989-12799, 12774-12585, 1 Frac in 46 stages w/ 1434951 Schlumberger, RIH & cleanou	andonment Notices must be fil inal inspection. to PBTD @ 21664'. Pres 589-21400, 21374-21188 20084-19895, 19869-1968 18579-18390, 18364-1817 17074-16885, 16859-166 15569-15380, 15354-1516 14064-13875, 13846-1366 12559-12370, 12344-1218 0g slickwater and 1000g to g slickwater and 1000g to for initial potential.	ed only after all requirements, includ sure test 5-1/2" csg to 9800# , 21159-20970, 20944-20755, 30, 19656-19465, 19439-1925 75, 18149-17965, 17934-1774 70, 16642-16455, 16429-1624 35, 15139-14950, 14924-1473 360, 13636-13445, 13419-1323 355, 12129-11940, 11914-1172 7.5% HCl acid w/ 19294757# Gcccccccccccccccccccccccccccccccccccc	ling reclamation, have been complete for 30 minutes, 20729-20540, 50, 19224-19035, 15, 17719-17530, 10, 16214-16025, 35, 14709-14520, 30, 13204-13015, 25. Total 1150 holes. sand. 5/30/19 RD DISTRICT MOCD	B160-4 must be filed once and the operator has ECENED	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f RUPU 5/3/19, RIH & cleanout good test. RIH & perf from 215 20514-20326, 20299-20110, 2 19009-18820, 18794-18605, 1 17504-17315, 17286-17100, 1 15999-15810, 15784-15597, 1 14494-14305, 14252-14090, 1 12989-12799, 12774-12585, 1 Frac in 46 stages w/ 14349511 Schlumberger, RIH & cleanou	andonment Notices must be fil inal inspection. to PBTD @ 21664'. Pres 589-21400, 21374-21188 20084-19895, 19869-1966 18579-18390, 18364-1817 17074-16885, 16859-1667 15569-15380, 15354-1516 14064-13875, 13846-1366 12559-12370, 12344-1215 0g slickwater and 1000g to t for initial potential. true and correct. Electronic Submission # For OXY USA imitted to AFMSS for proce CHAPMAN	ed only after all requirements, includ sure test 5-1/2" csg to 9800# , 21159-20970, 20944-20755, 30, 19656-19465, 19439-1925 75, 18149-17965, 17934-1774 70, 16642-16455, 16429-1624 35, 15139-14950, 14924-1473 355, 12129-11940, 11914-1172 7.5% HCl acid w/ 19294757# <b>Gc</b> Accepted for record - f 466974 verified by the BLM Well NCORPORATED, sent to the essing by PRISCILLA PEREZ of Title REGUL	ling reclamation, have been complete for 30 minutes, 20729-20540, 50, 19224-19035, 15, 17719-17530, 10, 16214-16025, 35, 14709-14520, 30, 13204-13015, 55. Total 1150 holes. sand. 5/30/19 RD DISTRICT MOCD	B160-4 must be filed once and the operator has ECENED	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f RUPU 5/3/19, RIH & cleanout good test. RIH & perf from 215 20514-20326, 20299-20110, 2 19009-18820, 18794-18605, 1 17504-17315, 17286-17100, 1 15999-15810, 15784-15597, 1 14494-14305, 14252-14090, 1 12989-12799, 12774-12585, 1 Frac in 46 stages w/ 14349511 Schlumberger, RIH & cleanou	andonment Notices must be fil inal inspection. to PBTD @ 21664'. Pres 589-21400, 21374-21188 20084-19895, 19869-1966 18579-18390, 18364-1817 17074-16885, 16859-1667 15569-15380, 15354-1516 14064-13875, 13846-1366 12559-12370, 12344-1215 0g slickwater and 1000g to t for initial potential. true and correct. Electronic Submission # For OXY USA imitted to AFMSS for proce CHAPMAN	ed only after all requirements, includ sure test 5-1/2" csg to 9800# , 21159-20970, 20944-20755, 30, 19656-19465, 19439-1925 75, 18149-17965, 17934-1774 70, 16642-16455, 16429-1624 35, 15139-14950, 14924-1473 360, 13636-13445, 13419-1323 355, 12129-11940, 11914-1172 7.5% HCl acid w/ 19294757# GCC $25$ Accepted for record - f 466974 verified by the BLM Well NINCORPORATED, sent to the assing by PRISCILLA PEREZ of Title REGUL Date 05/30/20 DR FEDERAL OR STATE (	ling reclamation, have been complete for 30 minutes, 20729-20540, 50, 19224-19035, 15, 17719-17530, 10, 16214-16025, 35, 14709-14520, 30, 13204-13015, 55. Total 1150 holes. sand. 5/30/19 RD DISTRICT MOCD	B160-4 must be filed once and the operator has ECENED	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f RUPU 5/3/19, RIH & cleanout good test. RIH & perf from 219 20514-20326, 20299-20110, 2 19009-18820, 18794-18605, 1 17504-17315, 17286-17100, 1 15999-15810, 15784-15597, 1 14494-14305, 14252-14090, 1 12989-12799, 12774-12585, 1 Frac in 46 stages w/ 14349511 Schlumberger, RIH & cleanou 14. I hereby certify that the foregoing is <b>Corr</b> Name ( <i>Printed/Typed</i> ) SARAH E Signature (Electronic S	bandonment Notices must be fil inal inspection. to PBTD @ 21664'. Pres 589-21400, 21374-21188 20084-19895, 19869-1966 18579-18390, 18364-1817 17074-16885, 16859-1667 15569-15380, 15354-1516 14064-13875, 13846-1366 12559-12370, 12344-1215 0g slickwater and 1000g T t for initial potential. true and correct. Electronic Submission # For OXY USA 1000 CHAPMAN Submission) THIS SPACE FC	ed only after all requirements, includ sure test 5-1/2" csg to 9800# , 21159-20970, 20944-20755, 30, 19656-19465, 19439-1925 75, 18149-17965, 17934-1774 70, 16642-16455, 16429-1624 35, 15139-14950, 14924-1473 30, 13636-13445, 13419-1323 35, 12129-11940, 11914-1172 7.5% HCl acid w/ 19294757# GCC 25 Accepted for record - f 4666974 verified by the BLM Well Accepted for record - f 4666974 verified by the BLM Well Accepted for record - f 11tle REGUL Date 05/30/20 DR FEDERAL OR STATE O Title ACCE	ling reclamation, have been complete for 30 minutes, 20729-20540, 50, 19224-19035, 15, 17719-17530, 10, 16214-16025, 55, 14709-14520, 55, 14709-14520, 55, 14709-14520, 55, Total 1150 holes. sand. 5/30/19 RD	alfo-4 must be filed once ed and the operator has ECENED IN <b>3.5</b> ? TH-ARTESIAO.C.D	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f RUPU 5/3/19, RIH & cleanout good test. RIH & perf from 219 20514-20326, 20299-20110, 2 19009-18820, 18794-18605, 1 17504-17315, 17286-17100, 1 15999-15810, 15784-15597, 1 14494-14305, 14252-14090, 1 12989-12799, 12774-12585, 1 Frac in 46 stages w/ 14349511 Schlumberger, RIH & cleanou 14. I hereby certify that the foregoing is Corr Name ( <i>Printed/Typed</i> ) SARAH E Signature (Electronic S Approved By	bandonment Notices must be fil inal inspection. to PBTD @ 21664'. Pres 589-21400, 21374-21188, 20084-19895, 19869-1968 18579-18390, 18364-1817 17074-16885, 16859-1667 15569-15380, 15354-1516 14064-13875, 13846-1366 12559-12370, 12344-1219 Og slickwater and 1000g T t for initial potential. true and correct. Electronic Submission # For OXY USA mitted to AFMSS for proce CHAPMAN Submission) THIS SPACE FC	ed only after all requirements, includ sure test 5-1/2" csg to 9800# , 21159-20970, 20944-20755, 30, 19656-19465, 19439-1925 75, 18149-17965, 17934-1774 70, 16642-16455, 16429-1624 35, 15139-14950, 14924-1473 30, 13636-13445, 13419-1323 35, 12129-11940, 11914-1172 7.5% HCl acid w/ 19294757# GCC /2.5 Accepted for record - f 4666974 verified by the BLM Well INCORPORATED, sent to the assing by PRISCILLA PEREZ on Title REGUL Date 05/30/20 DR FEDERAL OR STATE COffice crime for any person knowingly and	ling reclamation, have been complete for 30 minutes, 20729-20540, 50, 19224-19035, 55, 17719-17530, 60, 13204-13015, 55, 14709-14520, 50, 13204-13015, 55, Total 1150 holes. sand. 5/30/19 RD	BIGENED ECENED IN 3.5 ? TIL-ARTESIAO.C.D	