

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTCarlsbad Field Office
NMLC028793CFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.***SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	6. If Indian, Allottee or Tribe Name
2. Name of Operator COG OPERATING LLC	7. If Unit or CA/Agreement, Name and/or No. NMNM88525X
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701	8. Well Name and No. BURCH KEELY UNIT 947H
3b. Phone No. (include area code) Ph: 432-686-4373	9. API Well No. 30-015-40637-00-S1
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 23 T17S R29E NENE 990FNL 330FEL	10. Field and Pool or Exploratory Area BURCH KEELY-GLORIETA-UPR YESC
	11. County or Parish, State EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Deepen
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Hydraulic Fracturing
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Plug and Abandon
	<input type="checkbox"/> Plug Back
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Recomplete
	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Water Disposal
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Well Integrity
	<input checked="" type="checkbox"/> Other Venting and/or Flaring

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Burch Keely Unit #947h
Burch Keely Sat D
Actual gas flared for this battery for 9/24/2018 TO 12/23/2018 is as follows:
(Permit approval: Electronic Submission #436614
Sept
Total for Battery = 2327 MCF
Oct
Total for Battery = 2556 MCF
Nov
Total for Battery = 0 mcf
Dec
Total for Battery = 0 mcf

RECEIVED

Accepted for record

JUL 23 2019

NIMOC
8/1/19
DISTRICT II-ARTESIA O.C.D.

14. I hereby certify that the foregoing is true and correct. Electronic Submission #471035 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 06/27/2019 (19PP2616SE)	
Name (Printed/Typed) SANDY BALLARD	Title SENIOR ADMINISTRATIVE ASSISTANT
Signature (Electronic Submission)	Date 06/27/2019

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By _____	Title Accepted for Record	Date JUL 11 2019
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office Jonathon Shepard Carlsbad Field Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Additional data for EC transaction #471035 that would not fit on the form

32. Additional remarks, continued

Number of wells to flare: (36)

BURCH-KEELY UNIT 35 30-015-20378
BURCH-KEELY UNIT 36 30-015-22093
BURCH-KEELY UNIT 39 30-015-25711
BURCH-KEELY UNIT 40 30-015-21367
BURCH-KEELY UNIT 41 30-015-20391
BURCH-KEELY UNIT 45 30-015-22572
BURCH-KEELY UNIT 64 30-015-03080
BURCH-KEELY UNIT 65 30-015-21267
BURCH-KEELY UNIT 67 30-015-21368
BURCH-KEELY UNIT 73 30-015-20795
BURCH-KEELY UNIT 212 30-015-27605
BURCH-KEELY UNIT 213 30-015-27606
BURCH-KEELY UNIT 223 30-015-27647
BURCH-KEELY UNIT 224 30-015-27648
BURCH-KEELY UNIT 258 30-015-28914
BURCH-KEELY UNIT 272 30-015-27783
BURCH-KEELY UNIT 318 30-015-32006
BURCH-KEELY UNIT 319 30-015-32092
BURCH-KEELY UNIT 320 30-015-32093
BURCH-KEELY UNIT 323 30-015-32211
BURCH-KEELY UNIT 330 30-015-32443
BURCH-KEELY UNIT 331 30-015-32697
BURCH-KEELY UNIT 337 30-015-32755
BURCH-KEELY UNIT 342 30-015-32710
BURCH-KEELY UNIT 397 30-015-35389
BURCH-KEELY UNIT 398 30-015-35399
BURCH-KEELY UNIT 399 30-015-35400
BURCH-KEELY UNIT 400 30-015-35246
BURCH-KEELY UNIT 414 30-015-36345
BURCH-KEELY UNIT 592 30-015-38560
BURCH-KEELY UNIT 593 30-015-38540
BURCH-KEELY UNIT 594 30-015-38559
BURCH-KEELY UNIT 596 30-015-38515
BURCH-KEELY UNIT 597 30-015-40882
BURCH-KEELY UNIT 601 30-015-38570
BURCH-KEELY UNIT 602 30-015-38644
BURCH-KEELY UNIT 604 30-015-40663
BURCH-KEELY UNIT 723 30-015-38650

Reason for flare: Unplanned Midstream curtailment. Plant shut down due to HLP or plant maintenance