| Submit One Copy To Appropriate District Office State of New Mexico | Form C-103 |
|---|--|
| District 1 Energy, Minerals and Natural Resources | Revised November 3, 2011 |
| 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 NM 88210 NM 88210 NM 88210 NM 88210 NM 88210 | WELL API NO. |
| 811 S. First St., Artesia, NM 88210 N/G 1 OIL CONSERVATION DIVISION | 30-015-24569 |
| District III South St. Francis Dr. | 5. Indicate Type of Lease STATE FEE |
| 1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe. NM 87505 | 6. State Oil & Gas Lease No. |
| District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS | B-1159 |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH | Sunray State 8. Well Number |
| PROPOSALS.) 1. Type of Well: Gas Well Other | 8. Well Number 2 |
| 2. Name of Operator | 9. OGRID Number |
| COG Operating LLC | 229137 |
| 3. Address of Operator 2208 W Main Artesia NM 88210 | 10. Pool name or Wildcat Red Lake; Qn-GRBG-SA |
| 4. Well Location | , , |
| Unit Letter <u>L</u> 2075 feet from the <u>South</u> line and 330 feet from the West line | |
| Section 27 Township 17S Range 28E NMPM Eddy County | |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) | |
| 3614' GR | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Da | ıta |
| NOTICE OF INTENTION TO: SUBS | SEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | |
| TEMPORARILY ABANDON | |
| PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT | |
| | _ |
| OTHER: | ady for OCD inspection after P&A |
| All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. | |
| A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the | |
| | |
| OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR | |
| UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. | |
| TERMINISTRATED ON THE MARKEN OBORT ACE. | |
| The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and | |
| other production equipment. Power Lines + Poles Not Removed Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. | |
| Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. | |
| If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed | |
| from lease and well location. | ction equipment and junk have been removed |
| All metal bolts and other materials have been removed. Portable bases have been removed. | red. (Poured onsite concrete bases do not have |
| to be removed.) | i i i i i i i i i i i i i i i i i i i |
| All other environmental concerns have been addressed as per OCD rules. But a Role Not Removed Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- | |
| Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- | |
| retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well | |
| If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure. | |
| location, except for utility's distribution infrastructure. | |
| When all work has been completed, return this form to the appropriate District office to sche | dule an inspection. |
| | • |
| SIGNATURE TITLE Regulatory Technician | DATE 8/9/2019 |
| TYPE OF PRINTS THE PUBLIC FILE. | DIJONE SEE SAC COAC |
| TYPE OR PRINT NAME Delilah Flores E-MAIL: dflores2@concho.com For State Use Only | |
| 2 9 Sa 22 1 2 Man | \mathbf{D} |
| APPROVED BY:TITLETITLE | DATE 8/14/19 |
| | |