Office GENERAL English	Energy, Minerals and Natural Resources		Form C-103 Revised November 3, 2011
1625 N. French Dr. Hobbs, NM 88240			WELL API NO.
625 N. French Dr., Hobbs, NM 88240 District II 611 S. First St., Artesia, NM 8821006 1 2 2 C 9 OIL CONSERVATION DIVISION District III 000 Rio Brazos Rd., Aztec, NM 87410 District IV 220 S. St. Francis Dr., Santa Fe, NM 87505 220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS		DIVISION	30-015-24848 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		7505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Strate			B-2071
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		NG Phillips State 8. Well Number	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			37
2. Name of Operator COG Operating LLC			9. OGRID Number 229137
3. Address of Operator		10. Pool name or Wildcat	
2208 W Main Artesia NM 88210 4. Well Location	208 W Main Artesia NM 88210		Artesia; Qn-Grbg-SA
Unit Letter <u>P</u> <u>1165</u> feet from the <u>South</u> line and <u>978</u> feet from the East line			
Section <u>27</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>Eddy</u> County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3655' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB I			—
OTHER: Image: Construction of the constr			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> <u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u>			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment. Anchors Not Remarced			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location. Burged Plastic Life Not Removed All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 			
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution infrastructure.	lease: all electric	cal service poles and	lines have been removed from lease and well
When all work has been completed, return this form to	the annronriate F	District office to sche	dule an inspection
			duie un mispection.
SIGNATURE	TITLE Re	gulatory Technician	DATE 8/9/2019
TYPE OR PRINT NAME Delilah Flores			
For State Use Only	L-MAIL: \underline{dm}	ores2@concho.com	РНОМЕ: 575-748-6946 С
APPROVED BY:	TITLE	DENIE	
Conditions of Approval (if any):	IIIUL		

(