

RECEIVED

Submit One Copy To Appropriate District

AUG 26 2019

State of New Mexico

Form C-103

Office

Energy, Minerals and Natural Resources

Revised November 3, 2011

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

DISTRICT II-ARTESIA O.C.D.

## OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-015-21780

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement Name  
Ryburn FZ

8. Well Number

1

9. OGRID Number

7377

10. Pool name or Wildcat

Atoka; San Andres

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

EOG Resources, Inc.

3. Address of Operator

104 South Fourth Street, Artesia, NM 88210

4. Well Location

Unit Letter M : 890 feet from the South line and 430 feet from the West line  
Section 22 Township 18S Range 26E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3353' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☐CASING/CEMENT JOB ☐☒ Location is ready for OCD inspection after P&A

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- ☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- ☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. *Trash Not Removed*
- ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. *Burred Power Lines Not Removed!*
- ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) *Old Concrete Not removed*
- ☒ All other environmental concerns have been addressed as per OCD rules.
- ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. **No, active pipeline(s) within EOG Y Resources gas system.**
- ☐ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure. **CVE has been notified. Attached document.**
- When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Robert Asher TITLE: Environmental Supervisor DATE 8/26/2019TYPE OR PRINT NAME: Robert Asher E-MAIL: Robert\_Asher@eogresources.com PHONE: 575-748-4217

For State Use Only

APPROVED BY: DENIED TITLE DENIED

Conditions of Approval (if any):

DATE 8/27/19

**Bob Asher**

---

**To:** Dwayne Pounds  
**Subject:** RE: Power Poles (Ryburn FZ #1)

RECEIVED

AUG 26 2019

DISTRICT/ARTESIA/C.D.


**From:** Dwayne Pounds <DPounds@cvecoop.org>  
**Sent:** Tuesday, April 23, 2019 3:07 PM  
**To:** Bob Asher <Bob\_Asher@eogresources.com>  
**Cc:** Matthew Rivera <MRivera@cvecoop.org>  
**Subject:** RE: Power Poles (Ryburn FZ #1 & #3)

**CAUTION:** This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Bob,

For the Ryburn FZ #1, all the poles and overhead conductor belong to Central Valley Electric Coop., Inc. CVEC is staking the requests for powerline removals in the order they are received and after they are staked CVEC will remove the powerline as soon as we have crews available to do so.

Thank you,  
Dwayne



**Dwayne Pounds**

Central Valley Electric Cooperative, Inc.  
Staking Engineer  
1403 N. 13th St.  
PO Box 230  
Artesia, NM 88211-0230  
✉ Email: [dpounds@cvecoop.org](mailto:dpounds@cvecoop.org)  
☎ Work: (575) 746-3571  
☎ Cell: (575) 748-7483  
☎ Fax: (575) 746-4219

---

**From:** Bob Asher [[mailto:Bob\\_Asher@eogresources.com](mailto:Bob_Asher@eogresources.com)]  
**Sent:** Thursday, April 18, 2019 1:22 PM  
**To:** Dwayne Pounds  
**Subject:** FW: Power Poles (Ryburn FZ #1)

Dwayne,

The below location(s) are P&A'd and have power poles needing to be removed. EOG mapping shows service to be CVE. If you could respond back stating these poles/wire are scheduled for removal then I can notify the NMOCD, please.

Ryburn FZ #1  
Section 22, T18S-R26E  
32.728651; 104.377050

GO SOUTH OF ARTESIA ON HIGHWAY 285 FOR 8 MILES TO COUNTY ROAD 41 (DAYTON ROAD)  
AND TURN EAST FOR 1 MILE, CONTINUE ON DAYTON ROAD, PAST LAKE ROAD (FOR  
APPROXIMATELY 400'),

THEN TURN LEFT ON CALICHE ROAD, CONTINUE NORTH FOR 0.2 MILES, THROUGH GATE (COMBO 1928), LOCATION IS ON THE RIGHT.

Ryburn FZ #3

Section 22, T18S-R26E

32.728831; 104.375257

GO SOUTH OF ARTESIA ON HIGHWAY 285 FOR 8 MILES TO COUNTY ROAD 41 (DAYTON ROAD) AND TURN EAST FOR 1 MILE, CONTINUE ON DAYTON ROAD, PAST LAKE ROAD (FOR APPROXIMATELY 0.3 MILES),

THEN TURN LEFT ON CALICHE ROAD, CONTINUE NORTH FOR 0.2 MILES AND TURN EAST GOING PAST THE

BATTERY, CROSSING THE CATTLEGUARD/GATE (COMBO 1928). THE LOCATION IS TO THE RIGHT.

Thank you,

**Robert Asher, Environmental Supervisor, S & E Department, EOG Resources, Inc. Artesia Division**

104 South Fourth Street, Artesia, NM 88210, 575-748-4217 (Office), 575-365-4021 (Cell)

**EOG Safety Begins with YOUR Safety**

