| Submit I Copy To Appropriate District Office | State of New Mexico | Form C-103 |
|---|---|--|
| District I - (575) 393-6161 | Energy, Minerals and Natural Resources | Revised July 18, 2013 WELL API NO. |
| 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 | | 30-015-40795 |
| 811 S. First St., Artesia, NM 88210 | OIL CONSERVATION DIVISION | 5. Indicate Type of Lease |
| <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec. NM 87410 | 1220 South St. Francis Dr. | STATE S FEE |
| <u>District IV</u> – (505) 476-3460 | Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | 7. Lease Name or Unit Agreement Name Stirling 7 C |
| 1. Type of Well: Oil Well Gas Well Other | | 8. Well Number 7 |
| 2. Name of Operator | | 9. OGRID Number 277558 |
| Lime Rock Resources II-A, L.P. | | |
| 3. Address of Operator | | 10. Pool name or Wildcat |
| 1111 Bagby Street, Suite 4600 Houston, Texas 77002 | | Redlake: Glorieta-Yeso |
| 4. Well Location | | |
| Unit Letter <u>C</u> : | 990 feet from the <u>North</u> line and | 2130 feet from the West line |
| Section 07 | Township 18S Range 27E | NMPM NM County Eddy |
| | 1. Elevation (Show whether DR, RKB, RT, GR, etc. | |
| | 3295' GL | Line of the second of the seco |
| • • | propriate Box to Indicate Nature of Notice | • |
| TEMPORARILY ABANDON | PLUG AND ABANDON REMEDIAL WORD CHANGE PLANS COMMENCE DR MULTIPLE COMPL CASING/CEMEN | RILLING OPNS. P AND A |
| OTHER: | | ective Actions (Violation) |
| | ed operations. (Clearly state all pertinent details, an | |
| proposed completion or recom | i. SEE RULE 19.15.7.14 NMAC. For Multiple Co | ompletions: Attach wellbore diagram of |
| proposed completion of recom | piction. | • |
| Tubing has been moved off loc | eation. | |
| <u> </u> | • | RECEIVED |
| | | |
| | | |
| | | AUG 1 4 2019 |
| | | |
| | | districtil-artesiao.c.d. |
| | | |
| | | |
| | | |
| | | |
| Spud Date: | Rig Release Date: | |
| | | |
| | | |
| I hereby certify that the information about | ove is true and complete to the best of my knowled | ge and belief. |
| \cdot |) | • |
| SIGNATURE MASS | TITLE Production Superintende | ent DATE <u>08-7-19</u> |
| Type or print name Michael Barrett | ~ | kresources.com PHONE: 575-365-9724 |
| APPROVED BY: | TITLE Compliance | OHICEN DATE 8-14-19 |
| Conditions of Approval (if any): | | |

State Of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham

Governor

Sarah Cottrell Propst


Cabinet Secretary

Todd E. Leahy, JD, PhD

Deputy Cabinet Secretary

Adrienne Sandoval

Division Director



Field Inspection Program
"Preserving the Integrity of Our Environment"



LETTER OF VIOLATION - Field Inspection

01-Aug-19

LIME ROCK RESOURCES II-A, L.P.

1111 Bagby Street Suite 4600 Houston, TX 77002

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-015-40795] STIRLING 7 C #007

OGRID: 277558

C-07-18S-27E 990 FNL 2130 FWL

Inspection Date

Type Inspection

Inspector

Corrective Action Due By

Inspection No.

8/1/2019

Routine Inspection

[DRS] Danny Smolik

10/30/2019

iDRS1921336194

Violations:

Rule

Violation

19.15.10.8 Safety Procedures for Drilling and Production General Housekeeping Required

Comment:

Location needs tubing moved off location

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.