NM OIL CONSERVATION ARTESIA DISTRICT				
Submit One Copy To Approprie Tister 2019 State of New Mexico	Form C-103			
Office Energy Minerals and Natural Resources	Revised November 3, 2011			
District II	WELL API NO.			
	30-015-28877			
011 5. 1 list 5t., Altesia, 144 60210	5. Indicate Type of Lease			
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1000 Rio Brazos Rd., Aztec, NM 87410	STATE 🗌 FEE 🖂			
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Ryburn FZ			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number			
PROPOSALS.)	3: Well Number			
1. Type of Well: Oil Well Gas Well Other				
2. Name of Operator	9. OGRID Number			
EOG Resources, Inc.	7377			
3. Address of Operator 104 South Fourth Street, Artesia, NM 88210	10. Pool name or Wildcat Atoka; San Andres			
	Atoka, Sali Andres			
4. Well Location				
Unit Letter <u>M</u> : <u>990</u> feet from the <u>South</u> line and _	<u>990</u> feet from the <u>West</u> line			
Section 22 Township 18S Range 26E	NMPM Eddy County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3340' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Othe	er Data			
	UBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W	— — —			
	DRILLING OPNS. P AND A			
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🔲 CASING/CEM	IENT JOB			
	is ready for OCD inspection after P&A			
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 				
A steel marker at least 4 in traineter and at least 4 above ground level has been s	et in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER	OUARTER/OUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and	has been cleared of all junk, trash, flow lines and			
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
	emoved. (Foured onsite concrete bases do not have			
to be removed.) All other environmental concerns have been addressed as per OCD rules.				
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NM 	AC All fluids have been removed from non-			
retrieved flow lines and pipelines. No, active pipeline(s) within EOG Y Resources ga				

If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE	CIACUS.	_ TITLE:	Environmental Supervisor	_DATE_ <u>10/2/2019</u>

For State Use Only

 TYPE OR PRINT NAME:
 Robert Asher

 E-MAIL:
 _______ Robert Asher@eogresources.com

 PHONE:
 575-748-4217

APPROVED BY: Conditions of Approval (if any):

TITLE Statt mg. DATE 10/22/19