Form 3 (\$0-5)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137

Bi	Expires: Ja	anuary 31, 2018					
SUNDRY Do not use thi	5. Lease Serial No. NMLC028784A						
abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No. NMNM88525X						
Type of Well	8. Well Name and No. BURCH KEELY UNIT 956H						
Name of Operator COG OPERATING LLC	Contact: E-Mail: dking@con	DANA KING cho.com	9. API Well No. 30-015-42241-00-S1				
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701		3b. Phone No. (include are Ph: 432-818-2267	10. Field and Pool or Exploratory Area BURCH KEELY-GLORIETA-UPR YESO UNKNOWN				
4. Location of Well (Footage, Sec., T	11. County or Parish, State						
Sec 23 T17S R29E SENE 165 32.822641 N Lat, 104.036886	EDDY COUNTY, NM						
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATU	RE OF NOTICE	, REPORT, OR OTI	ER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	□ Deepen	☐ Produc	tion (Start/Resume)	☐ Water Shut-Off		
	☐ Alter Casing	☐ Hydraulic Fracturing ☐ Rec		ation	■ Well Integrity		
Subsequent Report Subsequent Re	□ Casing Repair	■ New Construction	on 🗖 Recom	plete	Other		
☐ Final Abandonment Notice	□ Change Plans	Plug and Aband	on 🔲 Tempo:	Temporarily Abandon Venting and ng			
	☐ Convert to Injection	□ Plug Back	Plug Back Water		" 5		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

BURCH KEELY UNIT 13C

PERMIT APPROVAL: ELECTRONIC SUBMISSION #446460

ACTUAL GAS FLARED FOR THIS BATTERY FOR 12/14/2018 TO 3/14/2019

NM OIL CONSERVATION ARTESIA DISTRICT

DECEMBER 2018 = 0 MCF

JANUARY 2019 = 2391 MCF

FEBRUARY 2019 = 0 MCF

Accepted for record

NMOCD LET SUPER RECEIVED

14. I hereby certify that tr	le foregoing is true and correct. Electronic Submission #484740 verifie For COG OPERATING L Committed to AFMSS for processing by PRI	.C, ser	t to the Carlsbad	
Name (Printed/Typed)	DANA KING	Title	SUBMITTING CONTACT	
Signature	(Electronic Submission)	Date	09/24/2019	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
Approved By		Title	Accepted for Record	SEP 2 5 2019
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	Jonathon Shepard Carlsbad Field Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

9 Q

Additional data for EC transaction #484740 that would not fit on the form

32. Additional remarks, continued

MARCH 2019 = 0 MCF

NUMBER OF WELLS TO FLARE: 20

BURCH KEELY UNIT 215 30-015-27573
BURCH KEELY UNIT 371 30-015-33801
BURCH KEELY UNIT 381 30-015-33806
BURCH KEELY UNIT 544 30-015-40322
BURCH KEELY UNIT 616 30-015-38517
BURCH KEELY UNIT 620 30-015-39569
BURCH KEELY UNIT 621 30-015-40325
BURCH KEELY UNIT 857 30-015-40381
BURCH KEELY UNIT 902 30-015-40329
BURCH KEELY UNIT 905 30-015-40540
BURCH KEELY UNIT 935H 30-015-42748
BURCH KEELY UNIT 936H 30-015-42789
BURCH KEELY UNIT 937H 30-015-42789
BURCH KEELY UNIT 944H 30-015-4279
BURCH KEELY UNIT 948H 30-015-44100
BURCH KEELY UNIT 948H 30-015-42723
BURCH KEELY UNIT 954H 30-015-42723
BURCH KEELY UNIT 955H 30-015-42724
BURCH KEELY UNIT 955H 30-015-42150
BURCH KEELY UNIT 956H 30-015-42150
BURCH KEELY UNIT 956H 30-015-42241

REASON: UNPLANNED MIDSTREAM CURTAILMENT PLANT SHUT DOWN DUE TO HLP OR PLANT MAINTENANCE