Submit 1 Copy To Appropriate District Office <u>District 1</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Form C-103 Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	OIL CONSERVATION 1220 South St. Fra Santa Fe, NM 8	ncis Dr.	WELL API NO. 30- 5. Indicate Type of Lea STATE 6. State Oil & Gas Lea	FEE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SWD			<ul> <li>7. Lease Name or Unit Agreement Name</li> <li>Loco Hills SWD 34</li> <li>8. Well Number 3</li> </ul>	
2. Name of Operator     COG Operating LLC	Gas Well 🛛 Other SWD			229137
3. Address of Operator 600 W. Illinois Avenue Midland, TX 79701			10. Pool name or Wildcat SWD;Wolfcamp 96135	
4. Well Location	1275 6.46 4. 6.4	· · · · ·		
Unit Letter J : Section 34	<u>1375</u> feet from the <u>South</u> Township 17S	line and Range 30		<u>East</u> line
	11. Elevation <i>(Show whether DR</i>			County Eddy
3526 GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	ITENTION TO:         PLUG AND ABANDON         CHANGE PLANS         MULTIPLE COMPL	REMEDIAL WOR		ERING CASING
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> <li>This was drilled to the Wolfcamp and completed in early 2010. In August 2019 this well was disposing at a rate of 3,750 BWPD at 1,479 PSI.</li> </ul>				
The well is currently down due to a suspected hole in the tubing (HIT). We would like to run a blanking plug to the packer so we can confirm whether we have a tubing leak or packer leak. If we have a hole in the tubing, pull and lay down all tubing for inspection. Replace any bad joints and run it all back while				
hydrotesting to 5,000 psi below the slips.				
If we have a packer leak, order kill mud and pull the packer. Run the same tubing design back.				
BLM 3160-5 NOI Sundry subm	nitted 9/3/2019.			SEP 0 4 2019
Spud Date:	Rig Release D	ate:		RECEIVED
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE HANN KI	ngTITLEPe	ermit Specialist II	DATE <u>9/3/</u>	2019
Type or print name <u>Dana King</u> For State Use Only	E-mail address	s: <u>dking@conch</u>	<u>o.com</u> PHONE:	(432) 818-2267
APPROVED BY: Dord Conditions of Approval (if any):	TITLE CON	mpliance	CAICEDATE J	0-21-19