NM OIL CONSERVATION		•
Submit One Copy To Appropriate District ARTESIA DISTRICTE Of No		Form C-103
District I OCE nergy, Minerals an	d Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II	<u>L</u>	WELL-API NO 30-015-02022
811 S. Eiret St. Artecio, NM 99210 OII, CONSERVA	TION DIVISION :	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	t. Francis Dr.	STATE X FEE 5. State Oil & Gas Lease No.
<u>District IV</u> Santa Fe, I	NM 87505	5. State Off & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		,
SUNDRY NOTICES AND REPORTS ON V	WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		STATE G
1. Type of Well: Oil Well Gas Well Other		3. Well Number #1
2. Name of Operator	(O. OGRID Number
EOG RESOURCES, INC		7377
3. Address of Operator		0. Pool name or Wildcat
PO BOX 2267 MIDLAND, TEXAS 79702	1	ARTESIA;QWN-GRYBRG-SAN ANDRES
4. Well Location		
Unit Letter_L_:_1570feet from the SOUTH line	and 250 feet from the WEST	line
Section 23 Township 18S Range 28E		ounty
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3545' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:	SUBSI	EQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
_	☐ COMMENCE DRILL	
PULL OR ALTER CASING	CASING/CEMENT J	ОВ
OTHER:	□	du fan OCD inamastian atta DOA
OTHER: Description Descri		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
ODED TOO WATER AND ON THE STATE OF THE STATE		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The state of the s		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment. By Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
Anchors, dead men, the downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's nit permit and closure	e battery and pit location(s) has produce	ave been remediated in compliance with
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
All metal bolts and other materials have been removed. Port	able bases have been remove	d. (Poured onsite concrete bases do not have
to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and wel		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE You Maddal THE	FLE. DECHI ATODY ODEC	NALIGE DATE 10/05/0010
SIGNATURE / Maddoy TI	ILE: KEGULATOKY SPEC	TALIST DATE 10/25/2019
TYPE OR PRINT NAME: KAY MADDOX E-MAIL: <u>kay_maddox@eogresources.com</u> PHONE: 432-686-3658		
For State Use Only		
DEMIED	DENIE	. / /
APPROVED BY:TI	TLE	DATE ///4/19
Conditions of Approval (if any):		/ '