RECEIVED New Mexico Submit 1 Copy To Appropriate District Form C-103 Office Energy, Minerals and Natural Resources Revised July 18, 2013 District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 OIL CONSERVATION DIVISION District II - (575) 748-1283 30-015-25271 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 STATE | FEE 🖂 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Artesia Gas Plant SWD PROPOSALS.) 8. Well Number #1 1. Type of Well: Oil Well Gas Well Other: Saltwater Disposal 9. OGRID Number 36785 2. Name of Operator DCP Midstream LP 3. Address of Operator 10. Pool name or Wildcat 370 17th Street, Suite 2500, Denver, CO 80202 Artesia Field Area 4. Well Location Unit Letter O: 330 feet from the South line and 2310 feet from the East line Range Section Township 18S 28E County Eddy 11. Elevation (Show whether DR. RKB, RT, GR, etc.): 3608 GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS.□ P AND A MULTIPLE COMPL П CASING/CEMENT JOB П **PULL OR ALTER CASING** DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: (Mechanical Integrity Test) OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. The MIT was conducted on Wednesday, November 13, 2019 at 9:00 am (MT). Dan Smolik, (NMOCD) was on site to provide oversight and approve the test. Below is a step-by-step summary of the MIT and the observed results: The annular space pressure between casing and tubing was not measured prior to the start of the MIT (no gauge). 1. Disposal was not occurring at the time of the test; the tubing pressure was 240 psi (crown gauge). 2. The annular space pressure was opened to a brine line (pump) and a calibrated chart recorder was installed. The annular pressure was bled down to 0 psi and the chart recorder was started at 9:22 am. 3. At 9:24 am the pressure was slowly increased by pumping brine from the truck to achieve a pressure of 580 psi. 4. The chart recorder and well were isolated from the pump truck and the MIT began at 9:27 am. 5. At 9:59 am (32 minutes) the annulus pressure was 550 psi, a loss of 30 psi (5.2% decrease). 6. 7. The brine was bled from the annulus to reduce the pressure to 0 psi and the chart recording was stopped. Prior to disconnection from the truck, the annular pressure was increased to 50 psi for normal operations. 8. Before the start of the MIT, a Bradenhead test was conducted by the NMOCD by opening the surface/production casing and production casing/tubing annulus valves to the atmosphere in order to observe and document the flow, if present. Please see the attached MIT pressure chart, NMOCD approval form, calibration sheet, and Bradenhead test documentation. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE A TITLE Consultant to DCP Midstream DATE <u>11/15/2019</u> Type or print name

APPROVED BY: Conditions of Approval (if any):

For State Use Only


Dale T Littleiohn

TITLE compliance officer

PHONE: (505) 842-8000 .

E-mail address: dale@geolex.com

DATE 11-19-19



State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary Designate

Todd E. Leahy, JD, PhD Deputy Secretary Gabriel Wade, Acting Director Oil Conservation Division



Date	e: <u>//-/3, 19</u>
API#	30-015-25271
A Mechanical Integrity Test (M.I.T.) was performed on, Well	Artesia SWD # OOL
M.I.T. is successful, the original chart has been retained becan of the chart with an attached Original C-103 Form indication District NMOCD field office. A scanned image will appear onling www.emnrd.state.nm.us/ocd/OCDOnllne.htm 7 to 10 days after	ating reason for the test, via post mail to ne via NMOCD website,
M.I.T. is unsuccessful, the original chart is returned to the Operator is to schedule for a re-test within a 90-day period. In non-compliance, all dates and requirements of the original are No expectation of extension should be construed because	If this is a test of a repaired well currently incressed in a test of a repaired well currently in a still in effect.
M.I.T. for Temporary Abandonment, shall include a de the location of the CIBP and any other tubular goods in the we status timeline.	etailed description on Form C-103, including ell including the Operator's request for TA
M.I.T. is successful, after the secondary request of a so Operator has within a 30-day period from the M.I.T. to submit the Chart, including a detailed description of the repair(s). One compliance be closed.	a current C-103 along with a legible scan of
M.I.T.is successful, initial of an injection well, you must 30 days. A C-103 form must include a detailed description of the position of the packer, tubing information, the date of fir	the work performed on this well Including

Please contact Rusty Klein at 575-748-1283 x109 for verification to ensure documentation requirements are in place prior to injection process.

If I can be of additional assistance, please feel free to contact me at (575) 748-1283 ext.

mank 10g,

Dan Smolik, Compliance Officer

EMNRD-O.C.D.

Injection volume.

District II – Artesia, NM

MACLASKEY

OILFIELD SERVICES

5900 WEST LOVINGTON HWY HOBES, N.M. 88240

THIS IS TO CERTIFY THAT:

DATE 11/19

	·	TECHNICAN	FOR MACLASKE	A Olivicin
I. Albert Rodin	COT_METER	TECTATIONS.	- HEIGHT FROM THE	ONTER LITE
L <u>Albert Kodra</u> SERVICES, MC.	HAS CHECKED			
TAICTOIL NATAT	, , , , , , , , , , , , , , , , , , , ,	1000	PRESSURE RECO	- المنابعة المال

SOO - 9150 -1800

TESTED AT TH		pressure.	200
PRESSURE_	CORRECTED	TEST AS FOU	ND CORRECT
TEST AS FOUNT		600	=
		<u>600 500</u>	+ : ====
100 300		200 800	
302 400		000 1000	
CON 500		-6.0	
CLOVC			l de la constant de l
REMARKS:		The state of the s	
in in the second			
	The same of the sa	and the second second	

SIGNED HELL TOLG

District II - Artesia

811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575-748-9720

E-mail Address: danny.smolik@state.nm.us

Phone: 575-626-0836

Witness:

Date: 11-13-19

State of New Mexico

Energy, Minerals and Natural Resources DepartmentOil Conservation Division Artesia District Office

Oil Conservation Division Artesia District Office						
BRADENHEAD TEST REPORT						
DCP COLUMN COMPANY LP Property Name Artesia SWD			. 20.0	30-015 25271		
DCP C	Pro	perty Name	1. 61	30-01	S. 252 W	Vell No.
Artecia	SWD	/			001	
		7. Surface Locatio	n			
1 ~ 1 1	nship Range	Feet from	N/S Line	Feet From	E/W Line	County
0 07 1	8 28	330		2310		Eddy
TA'D Well	SHUT-IN	Well Status INJECTOR	7	RODUCER	· · · · · · · · · · · · · · · · · · ·	DATE
		•	MD OIL		11-	13.19
YES NO	YES NO	INJ &	MD OIL	GAS	//-	15 19
-		OBSERVED DA	TA	J		
	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod C	asing	(E) Tubing
Pressure					······································	
Flow Characteristics	NA				_	
Puff	Y/ N	Y/ N	Y/ N		N (V	CO2
Steady Flow	Y/ N	Y/ N	Y/ N		Y/N	WTR
Surges	Y/ N	Y/ N	Y/ N		Y / 10	GAS
Down to nothing	Y/ N	Y/ N	Y/ N		Y / N	If applicable type
Gas or Oil	Y/ N	Y/ N	Y/N		Y / N	fluid injected for
Water	Y/ N	Y/ N	Y/ N		Y / N	Waterflood
		•		-		
If Braden head flowed water, o						
CLEAR	FRESH	SALTY	SULFU	JR	BLACK	
Remarks: Please state for e	each string (A, B, C, D, I	E) pertinent information reg	arding bleed dow	n or continuous b	oulld up if app	lies.
						•
		•				
Signature:			OIL CONSERVATION DIVISION			
Printed name: Danny Smolik		Entered	Entered RBDMS			
Title: Compliance Office O			Re-test	Re-test		

Phillips Petroleum Company
Artesia SWD Well No. 1
330 FSL, 2310 FEL, Section 7, T-18-S, R-28-E



Queen @ 1400'

San Andres @ 2150'

Lower San Andres @ 3370'

Glorieta @ 3760'

8 5/8" OD Casing @ <u>+</u>350' 12 1/4" hole Cmt to surface w/<u>+</u> 350 sx

2 7/8" OD Tubing @ \pm 3300' Plastic Lined

Baker Model AD-1 Packer @ +3300 Internally and Externally Plastic Coated

Injection Interval
+3350'-4000'

5 1/2" OD Casing @ ± 4100 ' 7 7/8" hole Cmt to surface w/ \pm 750 sx TD @ ± 4100 '