RECEIVED

Submit One Copy To Appropriate District Office DEC 0 3-2019 State of	bmit One Copy To Appropriate District fice DFC 0 3-2019 State of New Mexico		Form C-103 Revised November 3, 2011	
Office DEC 0 3 2019 State of New Mexico Office District I 1625 N. French Dr., Hobbs, NM 88240 District I			WELL API NO.	
District II 811 S. First St., Artesia, NM 88210 DISTRICTI-ARTESIACCOR SERVATION DIVISION			30-015-20680 5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease 1 LG-864	No.
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Boyd X State M Well 8. Well Number	
1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other			1	
2. Name of Operator EOG Resources, Inc.			9. OGRID Number 7377	
3. Address of Operator			10. Pool name or Wildcat	
104 South Fourth Street, Artesia, NM 88210			Seismic Monitor. Yeso	
4. Well Location Unit Letter F: 2080 feet from the North line and 1780 feet from the West line				
Unit Letter <u>F</u> : <u>2080</u> feet from the <u>North</u> line and <u>1780</u> feet from the <u>West</u> line Section 16 Township 19S Range 25E NMPM Eddy County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3485' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				OF. NG CASING □
TEMPORARILY ABANDON				4 🗆
OTHER: Description Location is ready for OCD inspection after P&A				
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LÉASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment. Burned Cable (W 5. de) Not Removed Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. Buried Roll (5 5. de) Not Removed. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.) — Tush —				
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines. No, active pipeline(s) within EOG Y Resources gas system.				
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE	TITLE: _	Environmental Sup	ervisor DATE_	12/3/2019
TYPE OR PRINT NAME: Robert Asher	E-MAIL:	Robert_Asher@ec	gresources.com PHONE	: <u>575-748-4217</u>
For State Use Only		DENIE	G C	. 11
APPROVED BY: Conditions of Approval (if any):	_TITLE	FOTA FORM AS WE AND PR	DATE	12/4/19