Office RECED	State of New Me		Form C-103
District I – (575) 393-6161	Energy, Minerals and Natu	iral Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OT CONCEDITION DESCRIPTION		WELL API NO. 30-015-32773
811 S. First St., Arte DE RM (883) 2019 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III – (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE .	
District IMPISARIFIANCO Santa Fe, NM 8/505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Redtailed Hawk 10H
1. Type of Well: Oil Well Gas Well Other			8. Well Number 1
2. Name of Operator			9. OGRID Number
VANGUARD OPERATING, LLC			258350
3. Address of Operator 5847 SAN FELIPE, STE. 3000, HOUSTON, TEXAS, 77057			10. Pool name or Wildcat Willow Lake; Delaware SW
4. Well Location			willow Lake, Delawate 3 w
Unit Letter C : 780 feet from the NORTH line and 2,610 feet from the WEST line			
Section 10 Township 25S Range 28E NMPM County Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
2969' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
			BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR TEMPORARILY ABANDON ☒ CHANGE PLANS ☐ COMMENCE DR			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN			
DOWNHOLE COMMINGLE	NOCTH LE GOWN L	O/ NO/ YOU WELL	
CLOSED-LOOP SYSTEM			
OTHER:		OTHER:	
	. SEE RULE 19.15.7.14 NMA		nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
Vanguard Operating, LLC is requesting to temporarily abandon (TA) this well to evaluate any future uphole recompletion opportunities. TA procedure is as follows:			
 MIRU WS. LD production equipment. RU WL. Set 4-1/2" CIBP @ 5,150' (Top perf @ 5,227). Cap w/ 35' of cement via bailer. 			
3. Contact NMOCD prior to running MIT test. Fill casing with treated water and pressure test to 500 psig for at least 30 minutes.			
Record pressure chart.			TA status may be granted after a
4. RD WS & WL.			successful MIT test is performed.
5. File subsequent C-103 and MIT chart. Temporary Abandoned Status approved until			Contact the OCD to schedule the test
	5-1-202	4	so it may be witnessed.
			· · · · · · · · · · · · · · · · · · ·
<u></u>			
Spud Date:	Rig Release D	ate:	
•			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE Operations Engineer DATE 11/20/2019			
SIGNATORE THE Operations Engineer DATE 11/20/2019			
Type or print name Kyle Zimmermann E-mail address: <u>kzimmerman@vnrenergy.com</u> PHONE: <u>432-202-0145</u>			
For State Use Only			
. 0			
APPROVED BY: Delice DATE 12-5-2019 Conditions of Approval (if any):			
Conditions of Approval (II ally).			

