	· .	
Submit One Copy To Appropriate District	te of New Mexico	Form C-103
Office		
1020 H. HONOR DI., HOUSS, HARTESIA DISTORT		
811 S. First St., Artesia, NM 88718 C 9 1 2010 OIL CONSERVATION DIVISION		N <u>30-015-10330</u> 5. Indicate Type of Lease
1000 Rio Brazos Rd Aztec NM 87410		STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, RECEIVED Santa Fe, NM 87505		6. State Oil & Gas Lease No. B-1159
87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name Sunray State
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well Gas Well Other		1
2. Name of Operator COG Operating LLC		9. OGRID Number 229137
3. Address of Operator		10. Pool name or Wildcat
2208 W Main Artesia NM 88210		Red Lake; Qn-GRBG-SA
4. Well Location		
Unit Letter <u>L</u> <u>1650</u> feet from the <u>South</u> line a		e
Section <u>27</u> Township <u>17S</u> Range <u>28E</u> 11. Elevation (S	how whether DR, RKB, RT, G	R etc.)
3681' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO		SUBSEQUENT REPORT OF:
' PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING MULTIPLE COM		
OTHER:		
All pits have been remediated in compliance with	OCD rules and the terms of th	on is ready for OCD inspection after P&A
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. $R_{W} = C_{W} = C_{W} + R_{W} +$		
from lease and well location. Burie & Cable Not Removed. Cove de All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.) Needs to be Removed - Not Covered Over All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.	icase. an electrical service pe	ses and mes have been removed from lease and wen
When all work has been completed raturn this form to	the appropriate District office	to askadula an inspection
When all work has been completed, return this form to		to schedule an inspection.
PLEASE SEE ATTACHED		
SIGNATURE	TITLE Regulatory Tecl	hnician DATE 12/30/2019
TYPE OR PRINT NAME Delilah Flores	E-MAIL: dflores2@conch	no.com PHONE: 575-748-6946
TYPE OR PRINT NAME Delilah Flores For State Use Only		
APPROVED BY:	TITLE	ENIED $DATE 1/6/20$
Conditions of Approval (if any):	IIILL k.	DAIL 1/ -/