RECEIVED						
Submit One Copy To Appropriate District Office State of New Mexico			Form C-103			
State of New Mexico Office District I 1625 N French Dr. Hobbs NM 1840 1155 State of New Mexico Energy Winerals and Natural Resource			Revised November 3, 2011			
1625 N. French Dr., Hobbs, NMENNRD OCD ADDITIONAL PROPERTY OF THE PROPERTY OF			WELL A	WELL API NO. 30-015-25061		
District I 1625 N. French Dr., Hobbs, NMEMORD CORRESTATION DIVISION District II 811 S. First St., Artesia, NM 88210 District III 1220 South St. Francis Dr.			5. Indica	5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE			
District IV Salita Fe, NIVI 8/303 1220 S. St. Francis Dr., Santa Fe, NM			6. State 0	Oil & Gas Lease No.		
87505	 					
SUNDRY NÔTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Williams			
PROPOSALS.)				8. Well Number		
1. Type of Well: Oil Well Gas Well P&A						
2. Name of Operator EOG Resources, Inc.			· I	9. OGRID Number 7377		
3. Address of Operator				10. Pool name or Wildcat		
104 South Fourth Street, Artesia, NM 88210			i	Atoka; Gorieta-Yeso		
4. Well Location						
Unit Letter <u>G</u> : <u>1980</u> feet from the	North	line and	1650	feet from the <u>East</u>	line	
Section 25 Township	18S Ran	nge 26	E NMPM	Eddy County		
11. Elevation (Show wh			, etc.)			
	3277' (7			
12. Check Appropriate Box to Indicate Nature of N	lotice, Rej	port or Oth	ier Data			
NOTICE OF INTENTION TO:		(SUBSEQUEI	NT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON		REMEDIAL	1	☐ ALTERING C		
TEMPORARILY ABANDON			DRILLING OPNS. P AND A			
PULL OR ALTER CASING MULTIPLE COMPL		CASING/CE	MENT JOB			
OTHER:	\neg	⊠ Locatio	l n is ready for Ω(CD inspection after Pa	&	
All pits have been remediated in compliance with OCD re						
Rat hole and cellar have been filled and leveled. Cathodi	ic protection	n holes have	been properly ab	oandoned.		
A steel marker at least 4" in diameter and at least 4' abov	e ground le	evel has been	set in concrete.	It shows the		
OPERATOR NAME, LEASE NAME, WELL NU	(MIRED AT	DI NIIMBEI	 	MARTER LOCATIO	ON OR	
UNIT LETTER, SECTION, TOWNSHIP, AND R	RANGE. A	II INFORM	ATION HAS B	EEN WELDED OR	JIV OK	
PERMANENTLY STAMPED ON THE MARKE			1			
The location has been leveled as nearly as possible to original ground contour and has been resolved as nearly as possible to original ground contour and has been resolved as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as the contour and has been leveled as the contour and has b						
other production equipment. Burned Power Line 10.+ Remainder Some Anchors, dead men, tie downs and risers have been cut off at least two feet below grounders.						
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with					ince with	
OCD rules and the terms of the Operator's pit permit and clos						
from lease and well location. Burned Caller All metal bolts and other materials have been removed. P	6 5 0	مه لا مه ام میره ام م	manna assad (Dassa	ad ansita agnarata hasa	a da not hava	
<u> </u>			removed. (Pour	d onsite concrete base	s do not nave	
to be removed.) All other environmental concerns have been addressed as per OCD rules.						
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMA				have been removed from	om non- `	
retrieved flow lines and pipelines. No active pipeline(s) within EOG Resources gas/water s				1.6.1	1 11	
If this is a one-well lease or last remaining well on lease:	all electrica	al service po	les and lines have	been removed from 16	ease and well	
location, except for utility's distribution infrastructure. When all work has been completed, return this form to the app	oropriate D	istrict office	 to schedule an in	spection.		
				-F		
SIGNATURE	TITLE:	Environment	al Supervisor	DATE <u>1/28</u>	<u>5/2020</u>	
TYPE OR PRINT NAME: Robert Asher	E-WVII ·	Robert Acl	ner@eogresource	s.com PHONE: <u>575</u>	-748-4217	
	P-MWIF.		1	GC	<u>, 70 7411</u>	
APPROVED BY: Conditions of Approval (if any):			ENIED		1 - 1	
APPROVED BY:	_TITLE		ha ii u	DATE_ 2 /	13/20	
Conditions of Approval (if any):				,	/	