

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUL 21 2006

OOD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 105 S 4 TH STREET		Telephone No. 505.748.1471
Facility Name MIMOSA AHS FEDERAL 3-Y	API Number 30 015 29123	Facility Type BATTERY

Surface Owner FEDERAL	Mineral Owner FEDERAL	Lease No.
--------------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter P	Section 4	Township 20S	Range 24E	Feet from the 635	North/South Line SOUTH	Feet from the 330	East/West Line EAST	County EDDY
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.59732 Longitude 104.58540

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 95 B/PW	Volume Recovered 90 B/PW
Source of Release PUMP FAILURE	Date and Hour of Occurrence 6/11/06 PM	Date and Hour of Discovery 6/11/06 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER VIA TELEPHONE	
By Whom? SHERRY BONHAM	Date and Hour 6/12/06 3:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

CHARGE MOTOR ON PUMP FAILED. REPAIRED CHARGE MOTOR.

Describe Area Affected and Cleanup Action Taken.*

APPROXIMATE 10' X 60' AREA WITHIN BERM AFFECTED. VACUUM TRUCK RECOVERED 90 BBL PRODUCED WATER. WILL ASSESS IMPACTED AREA FOR FURTHER ACTIONS.

SITE RANKING: 0

AFTER REVIEW OF SITE, NO FURTHER ACTIONS REQUIRED. REQUESTING CLOSURE.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sherry Bonham</i>		OIL CONSERVATION DIVISION	
Printed Name: Sherry Bonham		Approved by District Supervisor: TIM GUM by MB <i>Mike Bratcher</i>	
Title: Environmental Regulatory Agent		Approval Date: <i>2/17/06</i>	Expiration Date:
E-mail Address: sherryb@ypcnm.com		Conditions of Approval:	
Date: July 21, 2006 Phone: 505.748.1471		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary