

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rln Bruzas Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report☒ Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 105 S 4 TH STREET		Telephone No. 505.748.1471
Facility Name WHITE IU 2	API Number 30 015 22322	Facility Type BATTERY

Surface Owner FEE	Mineral Owner FEE	Lease No.
----------------------	----------------------	-----------

LOCATION OF RELEASE

Unit Letter 1	Section 28	Township 18S	Range 26E	Feet from the 1650	North/South Line SOUTH	Feet from the 330	East/West Line EAST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.71606 Longitude 104.37911

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 15 BBL/PW	Volume Recovered 0 BBL/PW
Source of Release PVC LINE	Date and Hour of Occurrence 11/20/06 8:00 AM	Date and Hour of Discovery 11/20/06 8:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

PVC LINE LEAKED. SHUT OFF WELLS AND CLOSED VALVES AT WATER TANKS.

Describe Area Affected and Cleanup Action Taken.*

APPROXIMATE 2' X 400' X 1" AREA AFFECTED. IMMEDIATELY SCRAPED IMPACTED MATERIALS AND HAULED TO DISPOSAL FACILITY. DEPTH TO GROUND WATER: >50' and <100', SURFACE WATER: 0, WELLHEAD PROTECTION: 0, SITE RANKING: 10.

NO FURTHER ACTIONS NEEDED. FINAL REPORT.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCDD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCDD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCDD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Sherry Bonham</u>	OIL CONSERVATION DIVISION TIM GUM by MB	
Printed Name: Sherry Bonham	Approved by District Supervisor: <u>[Signature]</u>	
Title: Environmental Regulatory Agent	Approval Date: NOV 29 2006	Expiration Date: <u>N/A</u>
E-mail Address: sherryb@ypenm.com	Conditions of Approval: <u>N/A</u>	Attached <input type="checkbox"/>
Date: November 22, 2006	Phone: 505.748.1471	

* Attach Additional Sheets if Necessary





White IU 2
Battery

LAKE ROAD

← Leak approximately 2/10 mile
north of intersection

EAST KINCAID RANCH ROAD



White IU 2

Sec. 28 T18S R26E

Eddy County, NM

RELEASE
NOVEMBER 20, 2006
LOCATION DIAGRAM
(Not to Scale)