

Submit 3 Copies To Appropriate District  
Office.  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1300 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Blvd., Aztec, NM 87410  
District IV  
1220 S. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
May 27, 2004

WELL API NO. 30-015-21204	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Nix Curtis BH	
8. Well Number 3	
9. OGRID Number 025575	
10. Pool name or Wildcat Penasco Draw San Andres Yeso	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3452' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> OTHER: <input type="checkbox"/>	
SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P & A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	

11/29/06 - Set a CIBP at 1343' with 35' cement on top. Spotted 25 sx cement at 1136'.

11/30/06 - Tagged at 860'. Spotted 25 sx cement at 358' and circulated 25 sx cement to surface. Cut off wellhead. Installed dry hole marker. Cleaned location. **WELL IS PLUGGED AND ABANDONED. FINAL REPORT.**

**Plugging of the well bore.  
Liability under bond is retained  
until surface restoration,  
environmental remediation and  
final inspection is completed.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Tina Huerta TITLE Regulatory Compliance Supervisor DATE December 1, 2006

Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471

**For State Use Only**

APPROVED BY: Gerry Guye TITLE Deputy Field Inspector DATE DEC 11 2006

Conditions of Approval (if any): District II - Artesia