

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
OCD - ARTESIA

WELL API NO.	30-015-34352
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.	VO-6902
7. Lease Name or Unit Agreement Name	Tuco BHE State Com
8. Well Number	1
9. OGRID Number	025575
10. Pool name or Wildcat	Eddy; Morrow

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other P&A <input type="checkbox"/>	
2. Name of Operator Yates Petroleum Corporation	
3. Address of Operator 105 S. 4 th Street, Artesia, NM 88210	
4. Well Location Unit Letter <u>A</u> : <u>1100</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line Section <u>2</u> Township <u>21S</u> Range <u>22E</u> NMPM <u>Eddy</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4063'GR	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>	
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____	
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/11/06 – POH with packer.

12/12/06 – Set a CIBP at 8648' with 35' cement on top. Spotted 25 sx cement at 7281'. Spotted 25 sx cement at 5248'. WOC.

12/13/06 – Tagged at 4950'. Spotted 25 sx cement at 3870'. WOC. Tagged at 3650'. Perforated at 2205'. Pressured up to 1000 psi. Spotted 25 sx cement at 2330'. WOC. Tagged at 2040'. Perforated at 1775'. Pressured up to 1000 psi. Spotted 25 sx cement at 1771'. WOC.

12/15/06 – Tagged at 1500'. Perforated at 435'. Pressured up to 1200 psi. Spotted 25 sx cement at 426'. WOC. Tagged at 250'. Perforated at 150'. Pressured up to 600 psi. RIH to 151'. Circulated 20 sx cement to surface. Cut off wellhead and installed dry hole marker. **WELL IS PLUGGED AND ABANDONED. FINAL REPORT.**

Plugging of the well bore.

**Liability under bond is retained
until surface restoration,
environmental remediation and
final inspection is completed.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Tina Huerta TITLE Regulatory Compliance Supervisor DATE December 27, 2006

Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471

For State Use Only

APPROVED BY: Gerry Guye TITLE Deputy Field Inspector DATE JAN 3 2007
Conditions of Approval (if any): District II - Artesia