

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

API # 30-015-23348

nLLB0631152750

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Chevron USA inc.	4323	Contact	Wayne Minchew
Address	HCR 60 Box 423 Lovington, NM 88260		Telephone No.	505-396-4414
Facility Name	Getty 24 Federal #1		Facility Type	Well location

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	NM
---------------	-----	---------------	-----	-----------	----

LOCATION OF RELEASE

RECEIVED

Unit Letter	Section	Township	Range	Feet from the	North Line	Feet from the	East Line	County
G	24	22 South	31 East	1980		1980		Eddy

DEC 21 2005

000-AMT1504

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Illegal Disposal of produced water	Volume of Release Est.	100 bbl.	Volume Recovered	0 bbl.
Source of Release	Unknown trucking company	Date and Hour of Occurrence	12/6/2005	Date and Hour of Discovery	12/6/2005 12:00 noon
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD & BLM		
By Whom?	Wayne Minchew	Date and Hour	12/6/2005 2:30 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Unknown Truck pulled to edge of location and emptied load of water off location into pasture.

Describe Area Affected and Cleanup Action Taken.*

- Pasture - None - soaked into sand

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>P.W. Minchew</i>	OIL CONSERVATION DIVISION		
Printed Name: P.W. Minchew	Approved by District Supervisor: TIM GUM by MB <i>[Signature]</i>		
Title: Operations Supervisor	Approval Date: <i>4/9/07</i>	Expiration Date:	
E-mail Address: pminchew@chevron.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>	
Date: 12/7/2005	Phone: 505-396-4414		

* Attach Additional Sheets If Necessary



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Chevron USA Inc.
HRC 60 / Box 423
Lovington, NM 88260
ATTN: Environmental Department

April 9, 2007

Reference: **Getty 24 Federal #1 24-22S-31E API # 30-015-23348 Eddy County, New Mexico**

Operator,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of an Initial Report Form C-141 reporting a release of produced fluids that occurred on or about December 6, 2005 at the above referenced well site. Please submit a work plan proposal (plan) for remediation, removal and/or clean up of contaminants that may be present at this site. The plan is to be formulated based on vertical and horizontal delineation of contamination, site ranking, and OCD Rules and Guidelines.

A publication outlining OCD guidelines and requirements for site ranking and spill remediation can be found on the OCD website as follows: <http://www.emnrd.state.nm.us/ocd> Click on each of the following items as they appear:

- Publications
- Environmental Handbook
- Miscellaneous Guidelines
- Remediation of Leaks, Spills and Releases

Please submit this plan to the OCD District 2 office no later than May 9, 2007. Please include any remedial or clean up actions that have already been performed.

Remediation requirements may be subject to other federal, state, local laws and/or regulations.

If I can be of assistance in this matter, my contact information is listed below.

Sincerely,

Mike Bratcher
NMOCD District 2
1301 W. Grand Ave.
Artesia, NM 88210
(505) 748-1283 Ext.108
(505) 626-0857
mike.bratcher@state.nm.us

Tracking number: nLLB0631152750