

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Month - Year
JAN 11 2007
OCD - ARTESIA, NM

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

API# 30.015.27548
hLLB 0715540865

Release Notification and Corrective Action

OGRD#17891

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <u>Pogo Producing Company</u>	Contact <u>Pat Ellis</u>
Address <u>P.O. Box 10340 Midland, TX 79702</u>	Telephone No. <u>(432) 685-8148</u>
Facility Name <u>Sand Dunes 34 Federal # 8</u>	Facility Type <u>Well</u>

Surface Owner	Mineral Owner	Lease No. <u>NM-43744</u>
---------------	---------------	---------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>0</u>	<u>34</u>	<u>23S</u>	<u>31E</u>	<u>330'</u>	<u>FSL</u>	<u>1980'</u>	<u>FEL</u>	<u>Eddy</u>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <u>oil + water</u>	Volume of Release <u>15 BALS</u>	Volume Recovered <u>10 BALS</u>
Source of Release <u>stuffing box leak</u>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Answering Automated service</u>	<u>12-28-06 @ 4:00pm</u>
By Whom? <u>Pat Ellis</u>	Date and Hour <u>12-28-06 @ 6:00 pm</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NONE

Describe Cause of Problem and Remedial Action Taken.*

A valve was closed on wellhead causing stuffing box to pressure up and leak. The valve was opened and stuffing box repaired.

Describe Area Affected and Cleanup Action Taken.*

The area affected included well pad and small area of pasture. All free fluids were removed by vacuum truck. Highlander Environmental was contacted to evaluate + remediate spill area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Patrick L. Ellis</u>	Approved by District Supervisor: <u>TIM GUM</u> <u>MB</u> <u>Mike [unclear]</u>	
Printed Name: <u>PATRICK L. ELLIS</u>	Approval Date: <u>6/7/07</u>	Expiration Date:
Title: <u>EH+S Supervisor</u>	Conditions of Approval: <u>Remediation per</u> <u>OCD approved work plan</u>	Attached <input type="checkbox"/>
E-mail Address: <u>ellis@pogo-producing.com</u>		
Date: <u>1-4-07</u> Phone: <u>(432) 685-8148</u>		

* Attach Additional Sheets If Necessary