BECBIARD NW 8 8 800 5 001\0001

District | 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410
District IY
1220 S St Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr.

Form C-141 Revised October 10, 2003 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Santa Fe, NM 87505											
# 30.01	5.35	353	Rele	ease Notific	cation	and Co	rrective A	ction		,	
LB0716550319 OGRD#17891					OPERA [*]	ГOR	Initial Report Final Report				
Name of Co	ompany P	090 PROP	lucina	COMPANY		Contact PATRICK Ellis					
Address P.O. Box 10340 Midland Texas 79702 Telephone No. 432 685-8148											
Facility Name Gaines 28 Com # 1 Facility Type Drilling + Completion Well											
Surface Owner Mineral Owner						Lease No. NM 94651					
LOCATION OF RELEASE											
Unit Letter	Letter Section Township Range Feet from the Nor			th/South Line Feet from the		East/West Line County					
	28	245	29E	1120	F	NL	530	FEL	Eddy	<u> </u>	
LatitudeLongitude											
NATURE OF RELEASE											
Type of Release O: Volume of Release 120 8845 Volume Recovered 1/9 8845											
Source of Release Frag TANK							Date and Hour of Occurrence Date and Hour of Discovery				
Was Immediate Notice Given?							If YES, To Whom? 5-2/-07 6:00 AM Discovery				
Yes No Not Required							PAUL EVANS BLM phone MESSAGE Mike BRATCHER OCD Phone MESSAGE Date and Hour 5-22-07 3:00 pm				
By Whom? Parkick Ellis Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.				
Yes No						II TES, VC	nume impacting	uie watercourse.			
If a Watercourse was Impacted, Describe Fully.*											
Describe Cause of Problem and Remedial Action Taken.*											
Flow back employee Allowed Soo BBL FRAG tank to over flow during flow back operation. Spill was caused due to in Attention of employee during job. Describe Area Affected and Cleanup Action Taken.*											
Describe Area Affected and Cleanup Action Taken.* Spill was released on location pad. The pad was water saturated due to recent rainfall. All of the free standing product was picked up using Vacuum fruck. The soil was scrapped and piled on location. Soil samples will be taken to defermine Contamination. Extent. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
regulations a public health should their c or the environ	Il operators or the environment. In a	are required to conment. The ave failed to a	report an acceptance dequately CD accep	d/or file certain reports of a C-141 report investigate and re	elease no ort by the emediate	otifications are NMOCD made contamination	nd perform correct arked as "Final Roon that pose a three	nderstand that purs etive actions for rele eport" does not reli eat to ground water responsibility for co	eases which ma eve the operator, surface water	ny endanger or of liability , human health	
							OIL CONS	<u>SERVATION</u>	DIVISION		
Signature: Latrick L. Ellis						IM GUM					
Printed Name	PATRI	ek L.	Ellis		/	Approved by District Supervisor: OY MB					
Title: EH+S Supervisor						Approval Date: (1/4/ 1/07 Expiration Date:					
E-mail Address: Ellis C pogo producing . Com						Conditions of	7				
Date: 5-2		, 5 ,-		(432) 685-8/48	9				Attached		



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor
Joanna Prukop
Cabinet Secretary

Mark E. Fesmire, P.E.
Director
Oil Conservation Division

Pogo Producing Company P.O. Box 10340 Midland, TX 79702 ATTN: Environmental Department June 14, 2007

Reference

Gaines 28 Com #1 28-24S-29E API # 30-015-35353 Eddy County, New Mexico

Operator,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of an Initial Report Form C-141 reporting a release of produced fluids that occurred on or about May 21, 2007 at the above referenced well site. Please submit a work plan proposal (plan) for remediation, removal and/or clean up of contaminants that may be present at this site. The plan is to be formulated based on vertical and horizontal delineation of contamination, site ranking, and OCD Rules and Guidelines.

A publication outlining OCD guidelines and requirements for site ranking and spill remediation can be found on the OCD website as follows: http://www.emnrd.state.nm.us/ocd Click on each of the following items as they appear:

- Publications
- Environmental Handbook
- Miscellaneous Guidelines

RATCHA

Remediation of Leaks, Spills and Releases

Please submit this plan to the OCD District 2 office <u>no later than Sept. 14, 2007</u>. Please include any remedial or clean up actions that have already been performed.

Remediation requirements may be subject to other federal, state, local laws and/or regulations.

If I can be of assistance in this matter, my contact information is listed below.

Sincerely.

Mike Bratcher NMOCD District 2 1301 W. Grand Ave. Artesia, NM 88210 (505) 748-1283 Ext.108 (505) 626-0857

(303) 020-0037

mike.bratcher@state.nm.us

Tracking number: nLLB0716560319