Submit 3 Copies To Appropriate District  State of New Mexico				Form C-103
Office	Office Energy Minerals and Natural Recourses			
District I 1625 N Erench Dr., Hobbs, NM 88240	bhergy, withertais and react	·	WELL API NO.	May 27, 2004
District II 1301 W. Grand Ave Ares a MM 88210	1220 South St. Francis Dr		30-015-27	
District III			5. Indicate Type of Leas	FEE 🛛
1000 Rio Brazos Rot. Azzer NM 87410 District IV	Danta 1 0, 1111 0 / 505		6. State Oil & Gas Lease	
1220 S. St. Francis Dr. Santa NM 87505				
	CES AND REPORTS ON WELLS	<u> </u>	7. Lease Name or Unit A	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			John AC	
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other P&A			8. Well Number	
		<del>յլյլ 11 2007</del>	7	
2. Name of Operator Yates Petroleum Corporation	an .	001	9. OGRID Number 02557	5
3. Address of Operator			10. Pool name or Wildo	
105 S. 4 <sup>th</sup> Street, Artesia, NM 88210			South Dagger Dray	v Upper Penn
4. Well Location Unit Letter E: 1980 feet from the North line and 660 feet from the West line				
Section 14	Township 20S Ra	inge 24E	NMPM Eddy	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3635'GR				
Pit or Below-grade Tank Application or Closure Distance from recreat freely make a point and the Comment and t				
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water  Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK			<del></del>	RING CASING 🔲
TEMPORARILY ABANDON				AND ABANDON 🖾
PULL OR ALTER CASING	MOLTIPLE COMPL []	CASING/CEMEN	I JOB	
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
7/3/07 – Set a CIBP at 7626'.				
7/5/07 – Tagged at 7626'. Circulated plugging mud. Spotted 25 sx cement at 7626'. Spotted 25 sx cement at 5660'. Spotted 25 sx				
cement at 3307'. Spotted 25 sx cement at 2067'. Spotted 25 sx cement at 1113'.				
7/6/07 – Tagged at 966'. Circulated		Dig out wellhead. I	nstalled dry hole marker.	WELL IS
PLUGGED AND ABANDONED. FINAL REPORT.				
Plugging of the well bore.				
Liability under bond is retained				
until surface restoration,				
environmental remediation and				
	1119	l inspection is	completed.	
				•
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-				
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .				
SIGNATURE TITLE Regulatory Compliance Supervisor DATE July 9, 2007				
Type or print name Tina Huert	E-mail address:	tinah@ypcnm.co	•	505-748-1471
For State Use Only	Burn	Gerry Guye		JUL 1 8 2007
APPROVED BY: TITLE Deputy Field inspector DATE				E 2007
Conditions of Approval (if any):	,	wanton is " Mile	791U	