Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-10:	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural I	Resources	May 27, 200 WELL API NO.	4
District II	OIL CONSERVATION DI	VICION	30-015-20501	
1301 W. Grand Ave., Artesia, NM 8010	1220 South St. Francis	Ι.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE S	4
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Banta I C, IVIVI 67505	´ '	6. State Oil & Gas Lease No.	
87505				
	S AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			0 . 7 . 11	
PROPOSALS.)			Santa Fe Land Improvement B. Well Number	\dashv
1. Type of Well: Oil Well Gas Well Other SWD		(1	
2. Name of Operator		9	9. OGRID Number	ᅱ
Yates Petroleum Corporation	AUO 0	0-2007	025575	
3. Address of Operator	· · · · ·	8 2007	10. Pool name or Wildcat	
105 S. 4 th Street, Artesia, NM	88210 OCD-A	RTESIA	SWD Canyon	_
4. Well Location	30 feet from the South	time and 66	60 feet from the East line	Ì
				
Section 17	Township 19S Range		NMPM Eddy County	100
	1. Elevation (Show whether DR, RK, 3395'GR	в, кт, ск, екс.)	31 1 2 1 1 1	
Pit or Below-grade Tank Application or C				
Pit type Depth to Groundwater	Distance from nearest fresh water v	vell Distar	nce from nearest surface water	
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Cons	truction Material	
12 Check An	propriate Box to Indicate Natur	e of Notice R	eport or Other Data	
12. Check rip	propriate Box to maleute I tatal		•	
NOTICE OF INTE			EQUENT_REPORT OF:	_
		MEDIAL WORK	/ _	_
 -		SING/CEMENT.	LING OPNS. PLUG AND ABANDON	J
PULL OR ALTER CASING	NOLTIPLE COMPL CA		new to wection	
OTHER:	□ Oī	איצוע HER: Mechanic	at Integrity Test.	
			give pertinent dates, including estimated da	
of starting any proposed work) or recompletion.	i. SEE RULE 1103. For Multiple Co	ompletions: Atta	ch wellbore diagram of proposed completion	on
r e				
7/19/07 – Pressure tested casing to 500 psi. Held for 30 min and tested good. No pressure lost.				
7/20/07 – Set nickel plated AS1-X 10K packer and 2-7/8" IPC tubing at 7709'. Loaded casing and pressure tested to 500 psi. Good chart.				
Original MIT chart attached.				
	0 0 4 6 56 5			
	Compliance ISSUE	17 (10)	(-	
Lhereby certify that the information abo	ove is true and complete to the best of	f my knowledge	and belief. I further certify that any pit or belov	
			an (attached) alternative OCD-approved plan	
11.				
SIGNATURE Charles	TITLE Regulatory Co	ompliance Supery	visor DATE August 6, 2007	
Type or print name Tina Huerta	E-mail address:t	inah@ypcnm.con	1 Telephone No. <u>505-748-1471</u>	
			-	
APPROVED BY: Puchaso	INS THE	ma Pl 1 Antras	Africal DATE 2/9/12	
Conditions of Approval (if any):	· / ··································	ing wipova	UNICO DATE OF 1707	-

