

District I - (505) 393-6161  
P.O. Box 1980  
Hobbs, NM 88241-1980  
District II - (505) 748-1283  
1301 W Grand Ave  
Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Road  
Aztec, NM 87410  
District IV - (505) 827-7131



State of New Mexico  
Energy Mineral and Natural Resources Department  
Oil Conservation Division  
1220 South St. Francis Drive  
Santa Fe, New Mexico 87505  
(505) 476-3440

AUG 27 2007  
OCD-A

Form C-141  
Originated 2/13/97

Submit 2 copies to  
Appropriate District  
Office in accordance  
with Rule 116 on  
back side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report

☒ Final Report

Name Marathon Oil Company	Contact T. Breninger
Address P.O. Box 1324 Artesia, NM/88210	Telephone No 505-457-2621
Facility Name Federal IBC Gas Com #2	Facility Type well

Surface Owner BLM	Mineral Owner BLM	Lease No
----------------------	----------------------	----------

LOCATION OF RELEASE

Unit Letter	Section 29	Township 21 S	Range 23 E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

NATURE OF RELEASE

Type of Release produced water	Volume of Release 19.7524	Volume Recovered 13		
Source of Release stuffing box leak	Date of Occurrence 08/07/07	Hour of Occurrence 4:30 AM	Date of Discovery 08/07/07	Hour of Discovery 6:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date of Notification		Hour of Notification	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			
If a watercourse was Impacted, Describe Fully (Attach Additional Sheets If Necessary)				
Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets if Necessary)				

The stuffing box leaked. The pumper shut the pumping unit down and closed the stuffing box rams. He called a vacuum truck. The alignment of the wellhead and the polish rod was checked. The polish rod was examined for surface damage, none was found. The stuffing box was repacked. The well is currently monitored 3 times daily.

Describe Area Affected and Cleanup Action Taken (Attach Additional Sheets if Necessary)

The total affected area was 8 feet by 100 feet with 1/2 inch penetration. The standing water covered an area of 7 feet by 100 feet with a depth of 2 inches. The standing water was removed by a vacuum truck.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulation all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Thomas T. Breninger</i>	<b>OIL CONSERVATION DIVISION</b> <b>ACCEPTED FOR RECORD</b>	
Printed Name: T. Breninger	Approved by <i>[Signature]</i> District Supervisor:	<i>[Signature]</i>
Title: Operations Superintendent	Approval Date: AUG 27 2007	Expiration Date: <i>[Blank]</i>
Date: 8/21/07	Phone: (505) 457-2621	Conditions of Approval: Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESIA