

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised March 17, 1999

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR


Initial Report  Final Report


Name of Company CBS OPERATING CORP.	Contact BENITO SANCHEZ
Address P O BOX 2236, MIDLAND, TX 79702	Telephone No. 432-557-1577
Facility Name BURNHAM UNIT WELL NO. 6-2	Facility Type BURNHAM UNIT WELL NO. 6-2
Surface Owner STATE OF NEW MEXICO	Mineral Owner CBS PARTNERS LTD
	Lease No. B-8146

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	2	17S	30E	660	south	1980	west	Eddy

NATURE OF RELEASE

Type of Release water w/skim of oil	Volume of Release 40 bbls. water	Volume Recovered none
Source of Release hole in casing	Date and Hour of Occurrence 9-22-03 ?	Date and Hour of Discovery 9-22-03 9:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gerry GuyeOCD called Benito Sanchez	
By Whom? BLM representative called OCD	Date and Hour 9-22-03 10:30 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Hole in casing-water leaking around wellhead and ran 300-400' beside road.		
Describe Area Affected and Cleanup Action Taken.* Area affected was around wellhead and approximately 350'+- down road, back hoe called out to clean up area. Poly pipe will be laid to bleed off pressure from well. Will test soil for remediation needs.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: M. A. Sirgo, III	Approved by District Supervisor:	
Title: Engineer	Approval Date:	Expiration Date:
Date: 9-22-03      432-685-0878	Conditions of Approval:	Attached <input type="checkbox"/>



\* Attach Additional Sheets If Necessary