Form 3160-5 (February 2005)

OCD-ARTESIA **UNITED STATES**

DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No 1004-0137 Expires March 31, 2007

5. Lease Serial No NM3606

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6 If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No. 27125		
I. Type of Well				8 Well Name and No		
1. Type of Well OII Well Gas Well Other OCT 23.2007 2 Name of Operator Fasken Oil and Ranch, Ltd. 30 Address			<u>~1 A</u>	Avaion 10 Federal No. 43		
2 Name of Operator Fasken Oil and Ranch, Ltd.				9 API Well No 30-015-31668		
3a Address 303 West Wall, Suite 1800 Midland, TX 7970	o. Phone No. <i>(include area d</i> 32 687-1777	code)	10. Field and Pool or Exploratory Area Catclaw Draw Delaware East			
4. Location of Well (Footage, Sec., T.,R, M., or Survey Description) 1817 FSL, 837 FEL, Sec. 10, T21S, R26E				11. Country or Parish, State Eddy, New Mexico		
12. CHEC	K THE APPROPRIATE BOX	(ES) TO INDICATE NATU	RE OF NOTIC	E, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION TYPE OF ACT				CION		
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Reco	uction (Start/Resume) imation implete	Water Shut-Off Well Integrity Other	,
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back		oorarily Abandon r Disposal		
Fasken Oil and Ranch, Ltd. propose A CIBP is set in the hole at 2954'. A abandon authority for this well after Fasken is reviewing this well for potential and the set of the se	copy of the chart will be pro the successful MIT has beer	vided to the BLM as soon a run.	as the testing			
SEE ATTACHED FO	R		"/	,		
CONDITIONS OF A	PPROVAL				TED FOR RECORD	
14 I hereby certify that the foregoing is tr	ue and correct			0(CT 25 2007	
Name (Printed/Typed) Jimmy D. Carlile		Title Regula	itory Affairs C	coordinatorGerry Guy NMOCD-	ve, Deputy Field Inspector -District II ARTESI/	.
Signatur Munic	Haure	Date 10/17/	2007			
	THIS SPACE F	OR FEDERAL OR S	TATE OFF	ICE USE	APPROVED	7
Approved by		Title	V VV.	D	OCT 2 1 2007	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon					WESLEY W. INGRAM]
Title 18 U S C Section 1001 and Title 43 fictitious or fraudulent statements or repre			and willfully to	make to any department	or agency of the United States	any false

Avalon 10 Federal #43 Fasken Oil and Ranch, Ltd. October 21, 2007 Conditions of Approval

Approval granted for MIT, which is to be performed within 30 days by 11/21/2007. Must be witnessed by BLM, contact 505-361-2822.

Subsequent sundry required requesting TA status.

TA status will be granted to 6/5/2008 with a successful MIT.

OCT 23 2007 OCD-ARTESIA

WWI 102107

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 505-234-5972

OCT 23 2007 OCD-ARTESIA

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 505-361-2822; Lea County 505-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for a 12 month period provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.

The TA status could be extended for an additional 12 month period without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative. The operator must submit a sundry notice requesting an extension of TA status 30 days prior to expiration of the previous approval and appropriate justification for extending the TA status is included.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.