

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCT 29 2007

OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-015-26536

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Range Operating New Mexico, Inc.	Contact: Steve Almager
Address: 100 Throckmorton Street Suite 1200	Telephone No. 505-631-0926
Facility Name: Candelario	Facility Type: SWD

Surface Owner Candelario Carrasco	Mineral Owner Candelario Carrasco	Lease No.
-----------------------------------	-----------------------------------	-----------

LOCATION OF RELEASE

Unit Letter D	Section 24	Township 22Ss	Range 37E	Feet from the 660	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	------------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Water	Volume of Release: 110	Volume Recovered: 100
Source of Release: Oil Tank	Date and Hour of Occurrence: 3:30 AM	Date and Hour of Discovery: 7:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Steve Almager	Date and Hour 10:00 AM 10-23-07	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Outside of firewalls. On the NW corner and West side of battery. Approximately 40' x 50' area on the NW corner and 75' x 50' area on the West. Picked up spill and will bring in an environmental company for assessment. Will remove wet soil and place place on plastic.

Describe Area Affected and Cleanup Action Taken *

Approximately 40' x 50' area on the NW corner and 75' x 50' area on the West. Picked up spill and will bring in an environmental company for assessment. Will remove wet soil and place place on plastic.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Linda C Stiles 		OIL CONSERVATION DIVISION	
Printed Name: Linda C. Stiles		Approved by District Supervisor. 	
Title: Sr Engineering Tech		Approval Date: OCT 29 2007 Expiration Date:	
E-mail Address: lstyles@rangeresources.com		Conditions of Approval:	
Date: 10-24-2007 Phone: (817) 869-4208		Attached <input checked="" type="checkbox"/>	

See Attached
Stipulations

* Attach Additional Sheets If Necessary

SPILL REPORT FORM – RANGE PRODUCTION COMPANY
USEPA REGULATION 40 CFR 112 / RRC SWR 8, 20 & 91

DATE SPILL DISCOVERED: 10-22-07	TIME: 1000am	NAME OF RESPONDER: Brian Cook	
LEASE WHERE SPILL OCCURED: Candalerio SWD		SOURCE OF SPILL (PIPELINE, TANK, ETC.): SWD Line	
COUNTY WHERE SPILL OCCURRED: Eddy		WEATHER CONDITIONS: Cold	
(IF KNOWN) SIZE OF SPILL:	DID SPILL REACH A DITCH OR STORM DRAIN? N/A	DID SPILL REACH NAVIGABLE WATERS, STREAM OR POND: N/A	
CAUSE OF SPILL AND REMEDIAL ACTION TAKEN: Poly line shrunk due to cold, causing the fused area to come apart due to shrinking because there was lack of slack. Called vacuum trk to pick up spill, will call environmental company to asses.			
TYPE OF DISCHARGE (OIL , WATER, FUEL, ETC): water	QUANTITY SPILLED (BBLs): 110bbls	DURATION OF SPILL: 1:30	
TIME SPILL CONTAINED: 1000am	DATE SPILL CONTAINED: Same as occurred	BBLs RECOVERED: 100bbls	
DEATHS/INJURIES/ACCIDENTS: N/A			
DESCRIBE AREA AFFECTED AND CLEANUP ACTION TAKEN: Outside of firewalls. On the NW corner and West side of Btry. Approximately 40x50' area on the NW corner and 75x50' area on the west. Picked up spill and will bring in an environmental company for assesment. Will remove wet soil and place on plastic.			
WITHIN COMPANY			
REPORTED BY: Brian Cook	TO: Steve Almager	TIME 1100am	DATE: 10-22-07
REPORTED BY: Steve Almager	TO: Linda Stiles	TIME: 900am	DATE: 10-23-07
AGENCIES NOTIFIED			
AGENCY:	REPORTED TO:	TIME	DATE:
NMOCD	Mike Bracher (VM)	1000am	10-23-07
USFS			
BLM			
RRC OF TEXAS			

Fill out this form the same day the spill event is discovered and FAX to:
SPCC Coordinator 100 Throckmorton Street, Suite 1200, Fort Worth TX 76102 (817) 869-9108

Guye, Gerry, EMNRD

From: Guye, Gerry, EMNRD
Sent: Monday, October 29, 2007 2:21 PM
To: 'lstiles@rangeresources.com'
Subject: Candelario SWD #1 (30.015.26536)

This office is in receipt of your C-141 on the produced water release, at this facility.

NMOCD Rule 19.15.3.116 states in part ... "The responsible person must complete **division approved corrective action** for releases which endanger public health or the environment. Releases will be addressed in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with Section 19 of 19.15.1 NMAC."

Information and tools for proper corrective action may be found in the Environmental Handbook on our web site www.emnrd.state.nm.us/ocd under the heading publications.

Remediation requirements may be subject to other federal, state and local laws or regulations.

Within 30 days, **on or before November 29, 2007**, completion of a remediation plan should be finalized and submitted to the Division, summarizing all actions taken to mitigate environmental damage related to the leak, spill or release, for approval.

Please be advised that NMOCD acceptance and/or approval of documents or work plans does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance and/or approval of documents or work plans do not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If I may be of further service or if you have any questions please feel free to contact me.

Gerry Guye

Compliance Officer

NMOCD - Artesia

Office (505)748-1283x105

Mobile (505)626-0843

E-Mail: gerry.guye@state.nm.us

10/30/2007