

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

OCT 31 2007 Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
OCD-ARTESIA side of form

30-015-33928 Release Notification and Corrective Action

OPERATOR

Initial Report X Final Report

Name of Company	Range Operating New Mexico, Inc.	Contact	Linda C. Stiles
Address	100 Throckmorton Street Suite 1200 Fort Worth TX 76102	Telephone No.	(817) 869-4208
Facility Name	Teledyne	Facility Type	Battery

Surface Owner	Mineral Owner	Lease No.	3001533928
---------------	---------------	-----------	------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	12	23S	28E	1980	SOUTH	990	WEST	Eddy

Latitude 32°19'05.44"N Longitude 104°02'44.69"W

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	72	Volume Recovered	65
Source of		Date and Hour of Occurrence	8-8-07	Date and Hour of Discovery	8:00 AM 8-8-07

Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher (NMOC) Jim Amos (BLM)
-----------------------------	---	------------------	-------------------------------------

	Date and Hour	8-9-07 2:00 PM
--	---------------	----------------

Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	NA
----------------------------	---	---	----

If a Watercourse was Impacted, Describe Fully.*	NA
---	----

Describe Cause of Problem and Remedial Action Taken.*	Water Transfer Pump Malfunction (Electricity Wire Grounded Out). Water Tanks Ran Over. Spill was contained within the firewall.
---	---

Describe Area Affected and Cleanup Action Taken.*	Water was contained inside firewalls. Called vacuum truck (Key Trucking). Recovered 65 bbls and hauled to disposal.
---	---

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Linda C. Stiles</i>	OIL CONSERVATION DIVISION	
Printed Name: Linda C. Stiles	Approved by District Supervisor: <i>[Signature]</i>	
Title: Sr. Engineering Tech	Approval Date: NOV 13 2007	Expiration Date:
E-mail Address: lstyles@rangeresources.com	Conditions of Approval: 2RP-15	Attached <input type="checkbox"/>
Date: 8-9-07	Phone: (817) 869-4208	

* Attach Additional Sheets If Necessary