District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources NOV 0 5 2007

OCD-ARTESIA

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141


Revised October 10, 2003

## Santa Fe, NM 87505 Release Notification and Corrective Action

Oil Conservation Division

1220 South St. Francis Dr.

ス	n ni	5 12		delease Moi	incat	OPERA			ial Report 🛛 Final Report	
30 015 33324  Name of Company: Southwestern Energy Company						OPERATOR Initial Report Final Report  Contact: Bruce Drummond				
Address: 2350 N. Sam Houston Parkway E. Suite 125						Telephone No. 505-631-8083				
Houston, Texas 77032						Telephone 110. 303-031-0003				
		oad Corral Co	entral Fac	cility	e: Tank Batter	у				
Surface Owner: New Mexico Mineral Owner:						New Mexico Lease No.				
LOCATION OF RELEASE										
Unit Letter	Section 2	Township 25 S	Range 29 E	Feet from the 330	North/ FSL	South Line	Feet from the 1980 /	East/West Line FEL	County Eddy	
<b>Latitude</b> 32.15278 <b>Longitude</b> -103.95262										
NATURE OF RELEASE										
Type of Release: Produced water						Volume of Release 20 bbls		1	Volume Recovered 70 bbls (mostly rainwater)	
Source of Release Fiberglass Produced Water Tank						Date and Hour of Occurrence Date and Hour of Discovery				
Was Immedi	ate Notice (		Yes	No Not R		If YES, To Whom? Mike Bratcher of the New Mexico Oil Conservation Division				
By Whom? Bruce Drummond						Date and Hour: 05/16/07 9:30 AM				
Was a Watercourse Reached?  ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.				
If a Watercourse was Impacted, Describe Fully.*										
Describe Cause of Problem and Remedial Action Taken.*										
During heavy Thunderstorm Lightning struck, set on fire, and destroyed (1) 500 BBL Fiberglass Produced Water Tank. Lease Operator arrived on location and was able to extinguish remaining fire. Lease Operator called out Vacuum Truck, recovered approx 70 bbls of fluid from Tank Bottom & inside Firewall, unable to determine total amount of Produced water released due to heavy accumulation of rain water inside Firewall. Lightning Protection will be installed.  9-4-07: Soil samples were gathered from the blended material and field tests were performed. Field analyticals showed the area to be blended within the NMOCD specified requirements. Composite samples from the blended material were gathered and prepared per EPA specifications and forwarded to Trace Analysis for official analyticals. Those official analyticals have been attached hereto.										
Describe Area Affected and Cleanup Action Taken.* Called out Vacuum Truck, recovered approx 70 bbls of fluid from Tank Bottom & inside Firewall Will run soil samples when it dries out.										
regulations a public health should their or the enviro	Il operators or the envioperations hument. In a	are required to ronment. The lave failed to a	o report an acceptance dequately CD accep	nd/or file certain reports of a C-141 report investigate and reports of the contract of the co	elease nort by the emediate	otifications a e NMOCD m e contaminat	nd perform correct arked as "Final R on that pose a thr	ctive actions for re Report" does not re reat to ground water	rsuant to NMOCD rules and leases which may endanger lieve the operator of liability er, surface water, human health compliance with any other	
Signature: B. Wayne Wolder						OIL CONSERVATION DIVISION				
Printed Name: R. WAYNE HOLDER							Approved by District Supervisor:			
Title: HEE COORDINATOR						Approval Da	te:	Expiration	Date:	
E-mail Address: Wayne_holder@Swn, can  Date: 10-31-07 Phone: 281-618-7302						Conditions o	f Approval:		Attached	
Date: 10-31-07 Phone: 281-618-7302 2RP-14										
Attach Additional Sheets If Necessary										



Pure Gold B Fed # 17 330 FNL 800 FWL Sec 20 T235 R31E