District I 1625'N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr. Santa Fe. NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

DEC 5 2007

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

1220 S. St. Fran	cis Dr., Sant	a Fe, NM 8750:		Sa	nta Fe	e, NM 87505 OCD-ARTESIA					side d	of form	
Release Notification and Corrective Action													
30-015-24800						OPERA?	COR				Final	Report	
Name of Company CBS Operating Corp.						Contact M. A. Sirgo, III							
Address P O Box 2236 Midland TX 79702 Facility Name Burnham GB SA Unit 4							Vo. 432/685-		· · · · · · · · · · · · · · · · · · ·				
Facility Nar	ne Burn	ham GB S	A Uni	<u>t 4</u>	<u> </u>	Facility Type Producer well wellhead							
Surface Owner Mineral Owner						Lease No. B-36					5		
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/West Li	ine Cou	nty			
J ·	2	17S	30E	2630	sc	outh	2630	east	E	ddy			
LatitudeLongitude													
NATURE OF RELEASE													
Type of Release CL1						Volume of	····	Volu	me Recov	ered			
Source of Release Stuffing box leak						<del></del>	lour of Occurrence	e Date	and Hour	of Dis	covery		
Was Immedia	ate Notice (		V [	ING ET NOAD.		If YES, To	Whom?					1	
		. L.	ies [	No Not Re	equired								
By Whom?	nourse Page	ahad?				Date and H	lour olume Impacting t	the Waterneure					
Was a Watercourse Reached? ☐ Yes ☒ No						II IES, VO	nume impacing i	ine watercoms					
If a Watercourse was Impacted, Describe Fully.*													
NA,													
L - 1 priot													
Describe Cause of Problem and Remedial Action Taken.*  Leaking stuffing box.  Repair stuffing box.  Describe Cause of Problem and Remedial Action Taken.*  Well head areas shows Signs of Priority  Placed on Placed on Plastic.  Describe Area Afforded and Classon Action Taken.*													
Leaking stuffing box. PELEASES, Small PILE of Contain mate													
Repair stuffing box. Soil not placed on Plastic.													
Describe Are	a Affected	and Cleanup	Action Tal	ken.*					<del>,</del>				
Pemorro	oil ar	nd conta	minato	ed soil.			-						
					are F	a with	dean dirt						
Take to disposal. Replace affected area with clean dirt.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
				nd/or file certain r									
				ce of a C-141 repo									
	should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, or local laws and/or regulations.													
	1	1	// -	10			OIL CON	SERVATION	<u>ON DIV</u>	<u>'ISIC</u>	<u>)N</u>	İ	
Signature:	m	. / -	Ju	50				/					
	M. A.	Sirgo,	III	1		Approved by District Supervisor:					July		
			<del>-</del>			DEC 6 2007							
Title:	Engir					Approval Date: Expiration Date:							
E-mail Address: mastres@aol.com						Conditions of	Approval:		Att	tached			
Date:Dece	mber 5.	, 2007	432 Phone	2/685-0878						/	/ \		

\* Attach Additional Sheets If Necessary

Date:December 5, 2007

## Guye, Gerry, EMNRD

From: Guye, Gerry, EMNRD

Sent: Thursday, December 06, 2007 3:44 PM

To: 'mastres@aol.com'

Subject: C-141 on Burnham GB SA #4

This office is in receipt of your C-141 on the oil, at this facility.

The inspection revealed some historical spill in addition to the recent release. The quantities indicated more than 5 bbls had been allowed to release, which was not indicated on your C-141, this requires notification to the Division, and Remediation. In addition to hauling and disposal of the contaminated soil a complete delineation of the area, with samples, must be accomplished.

NMOCD Rule 19.15.3.116 states in part ..."The responsible person must complete **division approved**corrective action for releases which endanger public health or the environment. Releases will be addressed in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with Section 19 of 19.15.1 NMAC."

Information and tools for proper corrective action may be found in the Environmental Handbook on our web site www.emnrd.state.nm.us/ocd\_under the heading publications.

Remediation requirements may be subject to other federal, state and local laws or regulations.

Within 30 days, on or before January 5, 2008, completion of a remediation work plan should be finalized and submitted to the Division, summarizing all actions taken or to be taken to mitigate environmental damage related to the leak, spill or release, for approval.

Please be advised that NMOCD acceptance and/or approval of documents or work plans does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance and/or approval of documents or work plans do not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If I may be of further service or if you have any questions please feel free to contact me.

Sincerely,

## Gerry Guye

Compliance Officer NMOCD - Artesia Office (505)748-1283x105 Mobile (505)626-0843

E-Mail: gerry.guye@state.nm.us