

French Dr., Hobbs, NM 88240
Grand Avenue, Artesia, NM 88210
Brazos Road, Aztec, NM 87410
St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-144
June 1, 2004

For drilling and production facilities, submit to appropriate NMOC District Office.
For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes ☐ No ☐

Type of action: Registration of a pit or below-grade tank ☐ Closure of a pit or below-grade tank ☒

Owner: <u>Chevron USA</u> Telephone: <u>505-441-3749</u> e-mail address: <u>LTATE@Chevron.com</u> Address: <u>P.O. Box 2401 Ave. O France, New Mexico</u> Facility well name: <u>NEEF 13 Fed #17</u> API #: <u>30-025-35359</u> U/L or Qtr/Qtr Sec <u>13</u> T <u>225</u> R <u>31E</u> County: <u>Eddy</u> Latitude <u>015</u> Longitude NAD: 1927 ☐ 1983 ☐ Surface Owner: Federal ☒ State ☐ Private ☐ Indian ☐		
Pit Use: Drilling ☒ Production ☐ Disposal ☐ Backover ☐ Emergency ☐ Lined ☒ Unlined ☐ Liner type: Synthetic ☒ Thickness <u>20</u> mil Clay ☐ Pit Volume <u>11,000</u> bbl	Below-grade tank Volume: _____ bbl Type of fluid: _____ Construction material: _____ Double-walled, with leak detection? Yes ☐ If not, explain why not: _____	
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.) <u>115 Ft</u>	Less than 50 feet (20 points) 50 feet or more, but less than 100 feet (10 points) <u>100 feet or more</u> (0 points)	<u>115 Ft</u>
Wetland protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes (20 points) <u>No</u> (0 points)	<u>0</u>
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet (20 points) 200 feet or more, but less than 1000 feet (10 points) <u>1000 feet or more</u> (0 points)	<u>0</u>
Ranking Score (Total Points)		<u>0</u>

If this is a pit closure: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if you are buying in place) onsite ☐ offsite ☐ If offsite, name of facility: _____ (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No ☒ Yes ☐ If yes, show depth below ground surface _____ ft. and attach sample results.

(5) Attach soil sample results and a diagram of sample locations and excavations.

Additional Comments: Had Tractor to location, remove all excess water and fluid, mix material to solidify, dig appropriate ditch or ditches, line ditches with approved liner, transfer material to ditches for deep bury, test pit area to make sure it meets OCD requirements, once passed we will bring in clean top soil and bring location back to original state

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☒ a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

Date: 10-15-07

Printed Name/Title: Cecil D. Tate, Construction REP. Signature: Cecil D. Tate

Your certification and NMOC approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.

Approval: Gerry Guye
Printed Name/Title: Compliance Officer

Signature: Gerry Guye

Date: OCT 15 2007

13R
225
31E



CONSTRUCTION INC.

3424 North WCR
Hobbs, New Mexico 88240


Office: (505) 393-5305
Facsimile: (505) 492-9845
- 24 Hour Service -

Sandblasting • Painting • Coating

Roustabout • Welding

Backhoe & Dump Truck Service

DOT Aluminum Tank Repair





CARDINAL LABORATORIES

PHONE (575) 383-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR RWI

ATTN: JUSTIN WRIGHT
3424 N. WEST COUNTY RD.
HOBBS, NM 88240
FAX TO: (575) 492-9845

Receiving Date: 12/14/07

Reporting Date: 12/14/07

Project Owner: CHEVRON

Project Name: NETT 13 FED #17

Project Location: RURAL EDDY COUNTY, NM

Analysis Date: 12/14/07

Sampling Date: 12/13/07

Sample Type: SOIL

Sample Condition: COOL & INTACT

Sample Received By: MLB

Analyzed By: KS

LAB NO.	SAMPLE ID	Cl ⁻ (mg/kg)
H13919-1	1A	< 16
H13919-2	2A	< 16
H13919-3	3A	96
H13919-4	4A	144
H13919-5	5A	< 16
Quality Control		500
True Value QC		500
% Recovery		100
Relative Percent Difference		< 0.1

METHOD: Standard Methods

4500-Cl⁻B

Note: Analyses performed on 1:4 w:v aqueous extracts.

John S. Moreno
Chemist

12-14-07
Date

H13919 RWI

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



ARDINAL LABORATORIES

101 East Marland, Hobbs, NM 88240 2111 Beechwood, Abilene, TX 79603
(505) 393-2326 FAX (505) 393-2476 (325) 673-7001 FAX (325) 673-7020

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Company Name: <u>PLUT</u>		P.O. #:	
Project Manager: <u>Justin W. Light</u>		Company: <u>PLUT</u>	
Address:		Attn:	
City: <u>Hobbs</u>		Address:	
Phone #: <u>293 5305</u>		City:	
Project #: <u>#17</u>		State: <u>Zip:</u>	
Project Name: <u>Nett 13 Fed #17</u>		Phone #:	
Project Location: <u>Rural Eddy County</u>		Fax #:	
Sample Name: <u>Justin W. Light</u>			
For Lab Use Only			

Lab I.D.	Sample I.D.	(G)RAB OR (C)DMP	# CONTAINERS	MATRIX						DATE	TIME			
				GROUNDWATER	WASTEWATER	SOIL	OIL	SLUDGE	OTHER:			ACID/BASE	ICE / COOL	OTHER:
H13919-1	1A	G	1											
-2	2A	G	1											
-3	3A	G	1											
-4	4A	G	1											
-5	5A	G	1											

PL/EAUSE NOTE: LUNAR and DUNAGAN, CAROLINA's history and client's earthwork records for any claim arising out of or based on this report shall be the client's responsibility for 30 days after completion of the applicable service. In no event shall the client be liable for incidental or consequential damages, including without limitation, business interruption, loss of use, or loss of profits incurred by the client, its subsidiaries, affiliates or joint ventures arising out of or based on the performance of services rendered by the client, regardless of whether such claim is based upon any of the above stated damages or other risks.

Relinquished By: <u>Justin W. Light</u>	Date: <u>12-14-02</u>	Received By: <u>Justin W. Light</u>
Relinquished By: <u>Justin W. Light</u>	Date: <u>12-14-02</u>	Received By: <u>Justin W. Light</u>
Time:		

Delivered By: (Circle One)	Sample Condition	CHECKED BY: <u>Justin W. Light</u>
Sampler - UPS - Bus - Other:	☐ Cool ☒ Intact ☐ Yes ☒ No ☐ Yes ☒ No	

5 X 6 1/2" x 2 1/2" → 12 1/2" W

ATTN: Gerry Guye

From: Justin Wright - RWI

PH: 575-441-5921

To get approval to Backfill pit

Approved
12-18-07
/ J.