

015 - 20912

Oil Conservation District
1301 W Grand
Artesia, NM 88210

JAN 30 2008
OCD-ARTESIA

Attention Ron Harvey
Inspection # iREH0727845214
Chi Operating
Arco Fed #001

This is to notify you that we have resolved the issues on this location.

We installed new well sign.

We cleaned location, repaired fence around stack pack and back dragged location.

Thank you,
Sonny Mann

Chi Operating
432-634-7062

*Inspected 11-19-07. New WS
installed. location was being cleaned
Inspected 1/31/08. Location
cleaned up. Compliance resolved.*

**Roadrunner Environmental
P.O. Box 1238
Carlsbad N.M. 88220**

Oil Conservation Division
1301 W. Grand
Artesia N.M. 88210

Attention: Mr. Ron Harvey
Inspection No. iREH0728245214
Chi Operating Inc.
ARCO FEDERAL No.001

Roadrunner Env ls submitting a plan to remediate the area around the tank battery

- 1st) Install new well sign with company name, API number, and proper legal description
- 2nd) Back drag location – clearing of weeds and mesquite
- 3rd) Chop all weeds around well, stack pack, separator, tank, and piping
- 4th) Pick up all debris, trash, and junk from location
- 5th) Dispose of at properly licensed landfill

Please feel free to contact me if you have any questions or concerns that I have not covered.

Thank you,

Mike Felkins
Roadrunner Env.
Off. 505-887-6067
Cell. 505-361-2774
