

015-35085

JAN 30 2008  
OCD-ARTESIA

Oil Conservation District  
1301 W Grand  
Artesia, NM 88210

Attention Ron Harvey  
Inspection # iREH0727843786  
Chi Operating  
Munchkin Fed # 010

This is to notify you that we have resolved the issues on this location.

We corrected all leaks, steamed cleaned the tanks, shoveled all contaminated grave out of berm area, steamed off the 20 mil liner. There are no breaches in the liner. Spread out clean gravel over liner.

Thank you,  
Sonny Mann

Chi Operating  
432-634-7062

*Inspected 1-10-08. Remediation  
looked to be completed, RON*

*1-31-08; Remediation completed,  
Compliance resolved RON*

**Roadrunner Environmental**  
**P.O. Box 1238**  
**Carlsbad N.M. 88220**

Oil Conservation Division  
1301 W. Grand  
Artesia N.M. 88210

Attention: Mr. Ron Harvey  
Inspection No. iREH0727843786  
Chi Operating Inc.  
MUNCHKIN FEDERAL NO.010

---

Roadrunner is submitting a plan of action to remediate the area inside the firewalls surrounding the tank battery.

This battery is built on top of a 20 mill liner that runs under the tanks and over the firewalls. I believe the liner has held the hydrocarbons on location as designed.

- 1<sup>st</sup>) Steam clean tanks and all piping on battery
- 2<sup>nd</sup>) Carefully shovel all contaminated gravel from top of liner
- 3<sup>rd</sup>) Wash down liner with clean well water and suck up with vac truck
- 4<sup>th</sup>) Spread clean gravel over liner

All contaminated material picked up on location will be hauled to a properly licensed disposal facility and disposed of in accordance with O.C.D. and B.L.M. requirements.

Please feel free to contact me if you have any questions or concerns.

---

Thank You,

Mike Felkins  
Roadrunner Env.  
Off. 505-887-6067  
Cell. 505-361-2774

---