

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

JAN 22 2008
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form
OCD-ARTESIA

30-015-26121

Release Notification and Corrective Action

MLB0626950367

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Chesapeake Operating, Inc. i47179	Contact Bradley Blevins
Address 1616 W. Bender, Hobbs, NM 88240	Telephone No. 505-391-1462, ext. 6224
Facility Name Carrasco 14 Well #1	Facility Type Tank Battery

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	14	23S	28E	1980	FNL	1880	FWL	EDDY

Latitude N 32 18.454 Longitude W 104 03.636

NATURE OF RELEASE

Type of Release Water & Oil	Volume of Release 12 bbls oil, 7 bbls water	Volume Recovered 10 bbls oil, 6 bbls water
Source of Release Oil line in battery	Date and Hour of Occurrence 9/22/06	Date and Hour of Discovery 9/22/06 7a.m
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD Artesia	
By Whom? Bradley Blevins	Date and Hour 9/22/06 9 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water dump plugged and pushed through oil lone from heater to tanks. Oil line developed hole inside the bermed area around tanks. Vacuum truck picked up 10 bbls of oil and 6 bbls of water. Leak was contained inside bermed area. Crew removed highly impacted soil.

Describe Area Affected and Cleanup Action Taken.*

Approximate area impacted is 95' x 30'. Soil removal was conducted and disposed of at NMOCD-approved disposal facility. After consultation and approval from M. Bratcher with the NMOCD, the site was lined with a 20 mil plastic liner and backfilled with clean soil. Pictures are attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Cliff P. Brunson*

Printed Name: Cliff P. Brunson for Chesapeake Operating, Inc.

Title: President

E-mail Address: cbrunson@bbcinternational.com

Date: 1/21/08

Phone: 505-397-6388

Approved by District Supervisor:

FEB 04 2008

Accepted for release
NMOCD

Approval Date:

u/a

Expiration Date:

u/a

Conditions of Approval:

u/a

Attached ☐

* Attach Additional Sheets If Necessary













