District | 1625 N French Dr., Hobbs, NM 88240 District | 1 1301 W Grand Avenue, Artesia, NM 88210 District | 11 1000 Rio Brazos Road, Aztec, NM 87410 District | 1V 1220 S. St Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

762503 Release Notification and Corrective Action																					
30-015-26930						OPERATOR Initial Report Final Report															
Name of Company Page Producing Co.  Address P.O. Box 10340 Midland TR 79702  Facility Name D. March 2 To the Page 100						Contact PAT Ellis															
Address P.O. Box 10340 Midland, Tx 79702							Telephone No. (432) 685-8100														
Facility Name D: Maggio Tank Battery Facility Type Tank Battery																					
Surface Ow	Surface Owner Mineral Owner							Lease 1	No. NM- 1	800											
LOCATION OF RELEASE																					
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/West Line	County												
J	16	265	29 E	1650	50	vth	1693	EAST	st Eddy												
Latitude_32 02 24.2 N Longitude_103 59 10.9 W																					
NATURE OF RELEASE																					
Type of Release $Oil$							Volume of Release 40 BBLS Volume Recovered 35 BBLS														
Source of Release TANK RAHERY							Date and Hour of Occurrence Date and Hour of Discovery														
Was Immediate Notice Given?						If YES, To Whom? /2-7-07 11:45 AM  NMOCO Gerry Guye 12-7-07 12:15 PM  BLM TERRY 7-7-07 12:15 PM															
By Whom? Johnny Burnett						Date and Hour /2-7-07 /2:/5 p.m															
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.															
If a Watercourse was Impacted, Describe Fully.*																					
Describe Cause of Problem and Remedial Action Taken.*																					
Oil production being produced to oil tank, tank filled up and equalizing line plugged up and allowed 40 BBLS of oil to overflow.																					
HILLS OF ON TO MATE OF ON TO ONEILION.																					
Describe Area Affected and Cleanup Action Taken.*																					
VACLUM	VACUUM truck WAS CALLED AND recovered 35 BBLS of oil. Backhoe WAS utilized to pick up AND remove saturated soil. High lander Environmental will take soil samples and review for Closure Workplan.																				
utilized	to p	ick up	And I	CAMOVE SA	furA.	ted so	il. Highly	ander Env	'IRON MENTA	/											
								nderstand that pur													
								tive actions for rel													
								eport" does not rel													
or the environ	should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other																				
federal, state,	or local lav	ws and/or regu	lations.		<del></del>		OH CON	GEDU ATION	DRUGION												
Signature: Ottuik I. Ellis  Printed Name: Parkick L. Ellis  A						Approved by District Supervisor:															
											Title E H+S Supervisor A						Approval Date: AN 2 2008 Expiration Date:				
											E-mail Address, e//isp@ pogo producing. Gom						Conditions of Approval:  Attached				
Date: /-2 * Attach Addit	L-08	ete If Names	Phone:	685-8100																	
ALLOW AUGI		LIS IT IVECESS	ar y A			•		2 R	P-136	2											
n GEGO	1241	47671	1					de	, , , , , ,	•											
P \$5080	5855	585																			