Oil Conservation District 1301 W Grand Artesia, NM 88210 MAR 1 3 2008 OCD-ARTESIA

Att: Mike Bratcher Inspection # iREH07278244523

Chi Operating

. ·

USA 9 Federal Com No. 002 Q

30-015-32202

9-20s-28e

This is to notify you that the corrective action is completed on this well. We repaired all leaks on tanks and cleaned them.

We dug out contaminated soil and tested. We then backfilled with clean soil. See attached analytical.

Thank you, Sonny Mann

MAR 2 4 2008

Accepted for record NMOCD

Signed By A



ANALYTICAL RESULTS FOR CHI OPERATING ATTN: SONNY MANN 7217 ROSWELL HIGHWAY ARTESIA, NM 88210 FAX TO: (575) 748-9015

Receiving Date: 02/23/08 Reporting Date: 02/26/08

Project Owner: CHI OPERATING Project Number: USA 9-2

Project Location: NOT GIVEN

Sampling Date: 02/21/08 Sample Type: SOIL

Sample Condition: INTACT Sample Received By: CK Analyzed By: CK/KS

LAB NUMBER SAMPLE ID		GRO (C ₆ -C ₁₀) (mg/kg)	DRO (>C ₁₀ -C ₂₈) (mg/kg)	CI* (mg/kg)
ANALYSIS DATE		02/25/08	02/25/08	02/25/08
H14316-1	BERM EAST	<10.0	319	112
H14316-2	BERM WEST	<10.0	<10.0	16
				,
Quality Control		446	520	500
True Value QC		500	500	500
% Recovery		89.2	. 104	100
Relative Percent Difference		7.9	5.2	<0.1

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Cl⁻: Std. Methods 4500-Cl⁻B *Analyses performed on 1:4 w:v aqueous extracts

Chemist

02/27/17 Date