

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street, Artesia, NM 88210	Telephone No. 505-748-1471	
Facility Name Mitchell SWD Transfer	API Number 30-015-22242	Facility Type Battery
Surface Owner Fee	Mineral Owner Fee	Lease No.

LOCATION OF RELEASE



Unit Letter D	Section 23	Township 17S	Range 25E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.82598 Longitude 104.45322

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 5 B/O & 8 B/PW	Volume Recovered 0 B/O & 0 B/PW
Source of Release Produced Water Tank	Date and Hour of Occurrence 4/19/2008 AM	Date and Hour of Discovery 4/19/2008 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully. N/A		
Describe Cause of Problem and Remedial Action Taken.* Blown CVE (power pole) fuse on transfer pump caused release from produced water tank, CVE called to replace fuse and crew called to clean up actions.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 15' X 30' on production pad and 20' X 50' outside pad. Contaminated soils scraped up and taken to an OCD approved facility, will treat area consisting of tilling and applying nitrogen fertilizer and micro blaze. Vertical and horizontal delineation will be made within sixty (60) days to determine if any further actions to be needed or will request closure. Depth to Ground Water: >100' (approx. 175'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Robert Asher	Approval Date: <u>5-9-08</u>	Expiration Date: <u>7-9-08</u>
Title: Environmental Regulatory Agent	Conditions of Approval: <u>STIPULATIONS</u>	
E-mail Address: boba@ypenn.com	Attached <input checked="" type="checkbox"/>	
Date: Tuesday, April 29, 2008	Phone: 505-748-4217	

* Attach Additional Sheets If Necessary

SEB0813056353

2RP-166p