(November 1994)

OCD ARTESIA

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

(G	


FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

Lease Serial No.

~	\sim	\sim		40	٠.
		11	4	42	

SUNDRY NOTICES AND	LC-065421	
Do not use this form for propo	6. If Indian, Allottee or Tribe Name	
abandoned well. Use form 316	0-3 (APD) for such proposals.	
		7. If Unit or CA/Agreement, Name and/or No
SUBMIT IN TRIPLICATE - Other instruct	tions on reverse side	
1. Type of Well	IIIN 1 6 2000	NM-111029
Oil Well X Gas Well Other	JUN 16 2008	8. Well Name and No.
2. Name of Operator	OCD-ARTESIA	Bradley 14 Federal Com No. 1
Cimarex Energy Co. of Colorado		9. API Well No
3a. Address	3b Phone No. (include area code)	30-015-32672
PO Box 140907; Irving, TX 75014-0907	972-401-3111	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R, M., or Survey Description)		White City; Penn (Gas)
1650' FNL & 990' FWL	11. County or Parish, State	
14-24S-26E		Eddy County, NM
12. CHECK APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NOTI	CE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Deepen Production (Start	/Resume) Water Shut-Off
Alter Casing	Fracture Treat Reclamation	Well Integrity
Subsequent Report Casing Repair	New Construction Recomplete	Other
Change Plans	Plug and Abandon X Temporarily Abar	ndon
Final Abandonment Notice Convert to Injection	Plug Back Water Disposal	
Attach the bond under which the work will be performed or provide the Bond following completion of the involved operations. If the operation results in a testing has been completed. Final Abandonment Notices shall be filed only determined that the site is ready for final inspection.) - Well-currently-has-GIBP @ 10610!-w/-2-sx-emt-covering Moperfs @ 10188'-10301.' TOC @ 10115.' On 02-20-08, tested casing to 590 psig for 40 minutes, cas receptionist notifying them of the test. Test was not witnesse Request TA status due to horizontal Cisco-Canyon and/or program in the White City; Penn area.	multiple completion or recompletion in a new intervalent after all requirements, including reclamation, have to brow perfs @-10650'-11832' and CIBP @ sing held. Danny Emerson, Cimarex field. horizontal Delaware potential. Cimarex for the control of the control	al, a Form 3160-4 shall be filed once been completed, and the operator has 2-10130' w/ 2 sx cmt covering Cisco Canyon ld representative, left a message with BLM
	(30 days)	
I hereby certify that the foregoing is true and correct	l-n-	JUN 18 2008
Name (Printed/Typed)	Title	Comme Comp Dometer World Incompation
Becky Nogelmeier	Operations Assistant	Gerry Guye, Deputy Field Inspector NMOCD District II ARTESIA
Signature	Date	
Kecky 1 solmin	May 30, 2008	ACCEPTED FOR RECORD
THIS SPACE FOR	R FEDERAL OR STATE OFFICE USE	
Approved by	Title	94N 1 2 2008
Conditions of Approval, if any, are attached. Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the subwhich would entitle the applicant to conduct operations thereon.		WESLEY W. INGRAM PETROLEUM ENGINEER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Bradley 14 Federal Com 1 Cimarex Energy Co. of Colorado June 12, 2008 Conditions

- 1. Notice of intent should have been sent requesting CIT with justification for request to TA well. Operator to provide justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 2. Please submit a sundry requesting CIT with justification within 30 days.
- 3. BLM to be notified at 575-361-2822 for Eddy County a minimum of 4 hours prior to a CIT.
- 4. Inadequate cement on CIBP at 10610'. BLM requirements state that 35' of cement bailed or 25 sacks pumped. NOI in 4/05/08 stated that 35' of cement would be placed on CIBP. Two sacks would get a maximum of 20'.
- 5. Inadequate cement on CIBP at 10130'. BLM requirements state that 35' of cement bailed or 25 sacks pumped.
- 6. If additional cement is not added at this time, it will be necessary to do it when the well is plugged, which could mean drilling out more than one CIBP.
- 7. See attached conditions for temporary abandonment.

WWI 061208

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging
 - b The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff
 - c All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for a 12 month period provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2 Describes the temporary abandonment procedure
- 3 Attaches a clear copy or the original of the pressure test chart.

The TA status could be extended for an additional 12 month period without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative. The operator must submit a sundry notice requesting an extension of TA status 30 days prior to expiration of the previous approval and appropriate justification for extending the TA status is included.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following.

- 1. A procedure to repair the casing so that a TA approval can be granted.
- A procedure to plug and abandon the well.

WWI 012908