Faxegry 108						
Faxes 1910						
State of New Mexico					Form	C-103
District Energy, Mineral: 1623 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources WELL API NO.				October	25, 2007
District II	OIL CONSERVATION DIVISION 30-015-00256					
District III 1220 Sout	1220 South St. Francis Dr.			of Lease		,
District IV Santa F	Santa Fe, NM 87505			as Lease !		
1220 S. St. Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name of RALPH NIX	ır Ünit Aş	reement	Name
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number	1		
2. Name of Operator			9. OGRID Numl	ber		
CHI OPERATING, INC. 3. Address of Operator	- JUL -8	2006	004378 10. Pool name o	r Wildest		
P.O. BOX 1799 MIDLAND, TX 79702	OCD-AR	TESIA	10. 1001 name 0	1 Wildcat		
4. Well Location						
Unit Letter J: 1980 feet from the SOUTH line at			ė			
Section 29 Township 18S Range 26E NM 11. Elevation (Show v				<u> </u>		
			Las a			
12. Check Appropriate Box to Indicate Nature of	Notice, Repor	t or Other D	ata			
NOTICE OF INTENTION TO:	1	SUBS	SEQUENT RE	PORT	OF:	. }
						ING 🗆 📗
TEMPORARILY ABANDON						
POLEON ALTEN CASING MIDERIPLE COMPL	LI CAS	NING/CEMENT	10B []			
OTHER: All pits have been remediated in compliance with OCD		Location is re	ady for OCD insp	ection al	iter P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.						
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the						
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR						
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR						<u> VA</u>
PERMANENTLY STAMPED ON THE MARK	ER'S SURFACE	4				
☑ The location has been leveled as nearly as possible to on	riginal ground cor	ntour and has b	een cleared of all	junk, tras	sh, flow l	ines and
other production equipment. Anchors, dead men, tie downs and risers have been cut	off at least two fa	at halasy aras-	nd laval			
If this is a one-well lease or last remaining well on lease	e, the battery and	pit location(s)	have been remedi	ated in co	mplianc	e with
OCD rules and the terms of the Operator's pit permit and ele- from lease and well location.	sure plan. All flo	w lines, produ	uction eq <mark>uipmen</mark> t a	and junk	nave beer	n removed
All metal bolts and other materials have been removed.	Portable bases ha	ve been remov	ved. (Poured onsite	e concrete	e bases d	o not have
to be removed.)				,		
 ✓ All other environmental concerns have been addressed ✓ Pipelines and flow lines have been abandoned in accord 	as per OCD rules lance with 19 15 9	9 714 B(4)(b) 1	NMAC All fluids	s have h o	en remos	ed from
non-retrieved flow lines and pipelines.		·	Till Lot, VIII Klond.	3 110 00		ied nom
When all work has been completed, return this form to the an inspection has to be made to a P&A location because it does	ppropriate Distric not meet the crite	t office to sche cria above, a p	edule an inspection enalty may be asso	n. If more	e ihan on	i¢
SIGNATURE Jan Corbet	_title_ <u>kez</u>	Cler	k	_DATE _	5/14	1/08
TYPE OR PRINT NAME <u>Fam</u> (or better	_E-MAIL: Par	nc@ch.	energyincum	PHONE:	432	<u>(p85</u> 500
APPROVED BY: / Sluy July	TITLE	Gerry G	uye	DATE	JUL	8 2008
Conditions of Approval (if any):		Complia	nce Officer	~		