District 1
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

JUN 1 U 2008 OCD-ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Form C-141

Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action (SEB081923003 **OPERATOR** nSEB0819231839 Initial Report Final Report Name of Company OXY USA WTP LP 192463 Contact Rick Kerby Address PO Box 1988 102 S Main Carlsbad NM 88220 Telephone No. (O) 505-887-8337 (C) 505-631-4972 Facility Name Big Walt CTB Facility Type Central Tank Battery Surface Owner BLM Mineral Owner Lease No. 30-015-33315 LOCATION OF RELEASE Unit Letter North/South Line Feet from the East/West Line Section Township Range Feet from the County **EDDY** Н 22 S 24 E Latitude Longitude **NATURE OF RELEASE** Volume of 600 Type of Release Water Volume Recovered 0 Source of Release Split in 8 in poly transfer line Date and Hour of Occurrence Date and Hour of Discovery 6:00PM 6:00PM If YES, To Whom? Was Immediate Notice Given? x□ Yes □ No □ Not NMOCD & BLM Required By Whom? Rick Kerby Date and Hour 06/07/2008 6:30 PM If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? ☐ Yes x☐ No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Separated weld in 8 in poly line. Split in Poly transfer line caused fluids to spill onto road and run into pasture. Describe Area Affected and Cleanup Action Taken.* All fluid ran down road and into pasture approximately \(\frac{3}{2} \) mile. Soil samples will be taken and analyzed and work plan formulated I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Remediation Actions to be completed and Final C-141 submitted with confirmation Approved by District Supervisor analyses/documentation on or before the Printed Name: Rick Kerby Expiration Date Approval Date: 7-908 Expiration Date: 9-9-08Title: HES Tech E-mail Address: rick_kerby@oxy.com Conditions of Approval: Attached Within 30 days, on or before **8-11-D\$** , completion of Date: 4-11-08 Phone: 631-4972 a remediation work plan based on delineation should be finalized and submitted for approval to the Division Attach Additional Sheets If Necessary

summarizing all actions taken and/or to be taken to mitigate environmental damage.

The plan must include general site characteristics, site ranking

score, soil remediation action levels, soil remediation methods,

http://www.emnrd.state.nm.us/ocd/documents/7C_spill1.pdf

document may be found at the following link:

and planned analytical testing for TPH, B-TEX, Chlorides or any other COCs as applicable. Please use the "Guidelines for Remediation of Leaks, Spills, & Releases" as your guide. This

SF80819232164

Notify OCD 48 hours prior to obtaining samples where analyses are to be presented to OCD