

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

JUL 18 2008
OCD-ARTESIA
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

SEB0821852969

NSEB0821852642

154903

OPERATOR

X Initial Report ☐ Final Report

Name of Company	St. Mary Land & Exploration Co.	Contact	Tom Morrow
Address	3300 N. A St. Bldg 7, Suite 200, Midland, TX 79705	Telephone No.	432-688-1773
Facility Name	ESDU Injection Station	Facility Type	Injection Station

Surface Owner	Bureau of Land Management	Mineral Owner	Bureau of Land Management	Lease No.
---------------	---------------------------	---------------	---------------------------	-----------

30 015 31350

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	24	18S	31E					

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Wtr.	Volume of Release	500 bbls	Volume Recovered	410 bbls
Source of Release	Fire destroyed water tanks & gun barrel	Date and Hour of Occurrence	7/16/08 6:00 AM	Date and Hour of Discovery	7/16/08 6:00AM
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos w/ BLM & Mike Bratcher w/NMOCD		
By Whom?	Bill Hearn	Date and Hour	5/30/08 10:01AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

CAUSE: Lightning struck injection station burning down (3) 500 bbl fiberglass suction tanks and scorching 750 bbl fiberglass gun barrel. Fill lines were broken away from tanks causing spill.

REMEDIAL ACTION: Notified all oil companies and shut-in all off lease water entering facility.

Describe Area Affected and Cleanup Action Taken.*

AFFECTED AREA: 85' X 45' = 3825 sq. ft. & 100' X 95' = 9500 sq. ft. Total = 13325 sq. ft. (Pasture Land)

CLEANUP ACTION: Picked up standing fluid w/vacuum truck. Waiting on orders from BLM/OCD for further cleanup remediation action.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Donna Huddleston</i>	OIL CONSERVATION DIVISION	
Printed Name: Donna Huddleston	Approved by District Supervisor: <i>TGum by SB</i>	
Title: Production Tech	Approval Date: <i>8-5-08</i>	Expiration Date:
E-mail Address: dhuddleston@stmaryland.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/> <i>2RP-208</i>
Date: 07/17/2008 Phone: 432-688-1789		

* Attach Additional Sheets If Necessary

SEB 0821853045